

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**Q799**

**Asset: CAMBRIA HEIGHTS ACADEMY - QUEENS, 188-04 91ST AVENUE, New York, 11423**

Inspection Id	Inspection Type	Time In	Last Edited
EE : Q799	Electrical	2024-03-25 8:22 AM	2024-04-01 1:19 PM

**Asset Data**

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Exit Lights, Local Sound System, LAN, Motor Controller (Motor Starter/Contactor, Variable Frequency Drive), Public Address System, IPDVS/CCTV System, Intrusion Alarm System, Service Switch, Switchboard
	Years: 2018
	Systems: Cafeteria (Projection System), Fire Alarm System, Lightning Protection
	Years: 2017
	Systems: Interior Lighting - Except (Science Rooms), Library, Auxiliary Signal/Bell System, Emergency Lighting, Security Lights
	Years: 2016
	Systems: Science Rooms, Grounding System
	Years: 2015
	Systems: Most Molded Case Circuit Breaker Type Panel Board
	Years: 2003, 2018

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

**Priority Condition**

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No condition recorded								

**Inspection**

Question	Response
<b>Electrical</b>	
<b>AUDITORIUM</b>	Does not Exist
<b>CAFETERIA</b>	Inspected
Instance on Basement	Inspected
<b>Lighting</b>	Inspected
Instance on Basement	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Basement	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Basement	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q799

Question	Response
<b>CAFETERIA</b>	
<b>Lighting</b>	
<b>Lighting Fixture - HID</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Basement	Does not Exist
<b>Local Sound System</b>	
Instance on Basement	Inspected
Installation Year	2018
Source of Installation	Inspector Estimate
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	
Instance on Basement	Does not Exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	
Does a Chandelier exist?	No
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Lighting Fixture - LED</b>	
<b>COMPUTER LAB</b>	
<b>GYMNASIUM</b>	
<b>KITCHEN</b>	
Instance on Basement	Inspected
<b>Lighting</b>	
Instance on Basement	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement	Inspected
<b>Pendant Mounted</b>	
Instance on Basement	Does not Exist
<b>Surface Mounted</b>	
Instance on Basement	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q799

Question	Response
<b>KITCHEN</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Basement	Does not Exist
<b>LIBRARY</b>	Inspected
Instance on Room 204	Inspected
<b>Lighting</b>	Inspected
Instance on Room 204	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 204	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Room 204	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on Room 204	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 204	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 204	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 204	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 204	Does not Exist
<b>Raceway With Receptacles</b>	Inspected
Instance on Room 204	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on Room 204	Does not Exist
<b>LOCKER ROOM</b>	Does not Exist
<b>MULTIPURPOSE ROOM</b>	Does not Exist
<b>SCIENCE DEMO ROOM</b>	Does not Exist
<b>SCIENCE LAB</b>	Inspected
Instance on Room 303	Inspected
Power Panel	Yes
Alternative use	No
Instance on Room 305	Inspected
Power Panel	Yes
Alternative use	No
<b>Lighting</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q799

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
Instance on Room 305	Inspected
Instance on Room 303	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 305	Inspected
Instance on Room 303	Inspected
<b>Pendant Mounted</b>	
Instance on Room 305	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 303	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 305	Does not Exist
Instance on Room 303	Does not Exist
<b>Recessed Mounted</b>	
Instance on Room 305	Does not Exist
Instance on Room 303	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 305	Inspected
Instance on Room 303	Inspected
<b>Pendant Mounted</b>	
Instance on Room 305	Does not Exist
Instance on Room 303	Does not Exist
<b>Surface Mounted</b>	
Instance on Room 305	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 303	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room 305	Does not Exist
Instance on Room 303	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 305	Does not Exist
Instance on Room 303	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 305	Does not Exist
Instance on Room 303	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 305	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 303	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q799

Question	Response
<b>SCIENCE LAB</b>	
<b>Emergency Shut-Off Power</b>	Inspected
Instance on Room 305	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 303	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	Inspected
Instance on Room 305	Inspected
Instance on Room 303	Inspected
<b>Instructor Unit</b>	
Instance on Room 305	Does not Exist
Instance on Room 303	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Room 305	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 303	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Student Unit</b>	
Instance on Room 305	Does not Exist
Instance on Room 303	Does not Exist
<b>Projection System</b>	Does not Exist
Instance on Room 305	Does not Exist
Instance on Room 303	Does not Exist
<b>SCIENCE PREP ROOM</b>	Inspected
Instance on Room 305A	Inspected
Power Panel	No
Alternative use	No
<b>Lighting</b>	Inspected
Instance on Room 305A	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 305A	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Room 305A	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Room 305A	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Room 305A	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Room 305A	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 305A	Does not Exist
<b>Lighting Fixture - LED</b>	

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q799

Question	Response
<b>SCIENCE PREP ROOM</b>	
<b>Lighting</b>	Inspected
<b>Lighting Fixture - LED</b>	
Instance on Room 305A	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	Inspected
Instance on Room 305A	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	Inspected
Instance on Room 305A	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	Does not Exist
Instance on Room 305A	Does not Exist
<b>SWIMMING POOL</b>	Does not Exist
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Does not Exist
<b>Recessed Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Does not Exist
<b>Recessed Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Replacement Quantity	25,000
Replacement Uom	S.F.
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not Exist
<b>EMERGENCY GENERATOR SET</b>	Does not Exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Does not Exist
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q799

Question	Response
<b>EMERGENCY LIGHTING</b>	
<b>Battery Pack</b>	
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Cafeteria
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Non Battery Pack</b>	
	Does not Exist
<b>EXIT LIGHT</b>	
	Inspected
<b>Battery Pack</b>	
Condition	Inspected
Deficiency	1 - Good
	No deficiencies recorded
<b>Non Battery Pack</b>	
	Does not Exist
<b>EXIT/EMERGENCY LIGHT</b>	
	Does not Exist
<b>FIRE ALARM SYSTEM</b>	
	Inspected
Replacement Quantity	25,000
Replacement Uom	S.F.
<b>Bell/Horn</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Area Smoke Detector</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>CO Detector</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Heat Detector</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	
	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q799

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Magnetic Door Holder/Contactor</b>	Does not Exist
<b>Fused Cutout Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Does not Exist
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Does not Exist
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards System Technology
Equipment	Fire Alarm Control Panel
Model	EST 3
Installation Year	2017
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not Exist
<b>Sub-Panel</b>	Does not Exist
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not Exist
<b>Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Printer</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Punch Register</b>	Does not Exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Does not Exist
<b>Tamper Flow Switch/Chain</b>	Does not Exist
<b>GROUNDING SYSTEM</b>	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>INTERCOM SYSTEM</b>	
Does not Exist	
<b>LAN</b>	
Inspected	
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	
Inspected	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>MOTOR CONTROLLER</b>	
Inspected	
<b>Motor Control Center</b>	Does not Exist
<b>Motor Starter/Contactor</b>	Inspected



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q799

Question	Response
<b>MOTOR CONTROLLER</b>	
<b>Motor Starter/Contactor</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Variable Frequency Drive</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>PANEL BOARD</b>	
<b>Fused Disconnect Switch Type</b>	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room 002
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Fused Toggle Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>PUBLIC ADDRESS SYSTEM</b>	
Replacement Quantity	25,000
Replacement Uom	S.F.
Instance	Telecom Room 309
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland Telecenter
Installation Year	2018
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
<b>SECURITY</b>	
<b>IPDVS/CCTV System</b>	Inspected
Replacement Quantity	25,000
Replacement Uom	S.F.
Installation Year	2018
Source of Installation	Inspector Estimate

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q799

Question	Response
<b>SECURITY</b>	
<b>IPDVS/CCTV System</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Intrusion Alarm System</b>	Inspected
Replacement Quantity	25,000
Replacement Uom	S.F.
<b>Central Control Panel</b>	Inspected
Instance	Custodian's Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-128BPT
Installation Year	2018
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting - Security</b>	Inspected
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>SERVICE SWITCH</b>	Inspected
Instance	Electrical Room 002
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	Service Switch #1, 2000amp/2000fuse
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	2018
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
<b>SWITCHBOARD</b>	Inspected
Number of Spares	2
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Electrical Room 002
Instance Condition	2 - Between Good and Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q799

Question	Response
<b>SWITCHBOARD</b>	
<b>Fused Disconnect Switch Type</b>	
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	N/A
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2018
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Does not Exist
<b>TELEPHONE SYSTEM</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	Does not Exist