Mechanical Inspe		MD CD PLP	C 0 05 05 1	AADII ODDDD	D Marr 37 - 1 - 44	425	Q99
			G Q, 85-05 1	44TH STREET	T, New York, 11	Time In	Last Edited
Inspection Id	Inspection  Mechanical					2024-01-10 8:30 AM	
ME : Q994 Asset Data	Mechanicai					2024-01-10 8:30 AM	2024-01-23 4:27 PM
Question					Answer		
Are there fuel tan	ke?				No		
		entries to the asset			0		
MERs/Fan Room		nuies to the asset			None		
Are there any spa		sing or Defective	CO Detectors?		No		
Are there any Em		-		1	No		
Are there any Pai					No		
Have any System	s/Major Build	ling Components	been upgraded?		Yes		
					Systems:	Electric Domestic Water Heater	
					Years:	2024	
					Systems:	Drinking Fountain (4 of 7)	
					Years:	2023	
					Systems:	Fixtures - Toilets, Urinals	
					Years:	2017	
Priority Condition							
Priority Pr Condition Exist Ca Last Year?	iority itegory	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title Status	PhotoImage
No condition recorde	ed						
nspection							
Question					Respons	se	
Mechanical							
AIR CONDITIO	ONING				Inspecte	d	
Chilled Water	System				Does no	Exist	
Condenser Wa	ater Distribu	tion: Piping, Pun	nps and Auxiliar	ries	Does no	Exist	
Cooling Coil in	n Ductwork				Does no	Exist	
Cooling Tower					Does no	Exist	
DX Split Syste					Does no		
Dry Cooler	<b></b>				Does no		
	e. T						
Packaged / Ro					Does no		
Packaged Terr	minal A/C				Inspecte	1	
Condition					3 - Fair		
Deficie	•	~			DEFECT:		
	eiency Locatio				Room T	10	
	eiency Quantit	y			1		
	tity Uom				EACH		
Potential Action				REPAIR			
Urgency of Action				PRIORI			
Purpose of Action				LEVEL			
Deficiency Photo1				_	recorded		
Violations				No viola	tions recorded.		
Refrigerant Leak Detection System				Does no	Exist		
Refrigerant Piping				Does no	Exist		
Return Fan				Does no	Exist		
CENTRAL ACID WASTE NEUTRALIZING TANK				Does no	Exist		
CENTRAL ACI	D WINDIE						

	D	
uestion	Response	
CLIMATE CONTROL SYSTEM		
COMPACTOR	Does not Exist	
CONVEYING	Does not Exist	
DOMESTIC WATER SYSTEM	Inspected	
Domestic Cold Water System	Does not Exist	
Domestic Hot Water System	Inspected	
Domestic Hot Water Remote Storage Tank	Does not Exist	
Domestic Water Heat Exchanger	Does not Exist	
Electric Domestic Water Heater	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Gas Fired Domestic Water Heater	Does not Exist	
Heat Pump Domestic Water Heater	Does not Exist	
Oil Fired Domestic Water Heater	Does not Exist	
Domestic Water Distribution Piping	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Does not Exist	
Sewage/Waste/Vent Piping	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not Exist	
Sump Pump	Does not Exist	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT	Does not Exist	
WATER)	Does not Exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
- Janitor Sink	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Urinal	Does not Exist	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not Exist	
Sink And Fountain Combo Unit	Does not Exist	
Toilet	Inspected	
Condition	1 - Good	

uestion	Response	
FIXTURES		
Student		
Toilet	Inspected	
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
GAS FIRED FURNACE	Does not Exist	
GAS SERVICE	Does not Exist	
HEATING	Inspected	
Heating Coil In Ductwork	Does not Exist	
Hydronic Heating	Does not Exist	
Radiator/Convector/Fin Tube	Does not Exist	
Steam Heating	Does not Exist	
Steam supplied by External Sources	Does not Exist	
Unit Heater/Cabinet Heater		
Condition	Inspected  3 - Fair	
Deficiency	DEFECTIVE CONTROLS	
Deficiency Deficiency Location/Instance	Corridor ceiling near Exits	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
HEATING PLANT	Does not Exist	
Enclosed IDF Room	Does not Exist	
KITCHEN	Does not Exist	
MDF Room	Does not Exist	
SCIENCE DEMO ROOM	Does not Exist	
SCIENCE LAB	Does not Exist	
SCIENCE PREP ROOM	Does not Exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Does not Exist	
SWIMMING POOL	Does not Exist	
VENTILATION	Inspected	
Is the building mechanically ventilated?	Yes	
Exhaust Fan	Inspected	
Approximate Total # of Fans	1-25	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Does not Exist	
Metal Ductwork	Inspected	
Are there any uninsulated ductwork by design in Mechanical Rooms?	No	
Are there chain operated dampers?	No	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	

Bullan	ing Condition Assessment But Vey 2023 - 2024	
Mechanical Inspection		Q994
Question	Response	
VENTILATION		
Unit Ventilator	Does not Exist	