Building Condition Assessment Survey 2023-2024

Asset:		ND PRE-K CENTER AT 127 I ISLAND, NY, 10309	75 WOODROW	V ROAD - STAT	EN ISLAND,	1275 WOOD	ROW
Inspection	Id Inspection Type				Time	In	Last Edited
32	295 MECHANICAL				2024	-02-16 12:33PI	M 2024-03-17 12:39AM
sset Data							
Question				Answer			
Have any S	Systems/Major Building C	Components been upgraded?		No Syster	n Upgraded		
Are there for	-			No			
Total # of v	water main service entries	to the asset		0			
MERs/Fan	Rooms Locations			None			
Are there a	ny spaces with Missing o	r Defective CO Detectors?		No			
	ny Painted/Obstructed Sp			No			
Are there as	ny Emergency Stop Swite	ches with Missing Hammers?		No compo	onents		
riority Con							
	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
	Category	Description	Affected	Description	Notified	Title	Image
No condition	on recorded						
nspection							
Question				Response			
Mechanica	al		<u> </u>				
AIR CO	NDITIONING			Inspected			
Chilled	l Water System			Does not	exist		
Conde	nser Water Distribution	Piping, Pumps and Auxiliarie	s	Does not	exist		
Cooling	g Coil in Ductwork			Does not	exist		
Cooling	g Tower			Does not	exist		
DX Spl	lit System			Does not	exist		
Dry Co				Does not			
Packag	ged / Rooftop Unit			Inspected			
	Instance			Roof			
	Instance Condition			2- Betwee	en Good and Fa	ir	
	Instance Quantity			2			
	Instance Quantity Uom	ı		EACH			
	Manufacturer			Trane			
	EquipmentId			ACCU-2,	ACCU-10		
	Capacity/Size Quantity			6			
	Capacity/Size UOM			Tons			
	Source of Capacity/Siz	e		Inspector	Estimate		
	Installation Year			2013			
	Source of Installation Y	/ear		Documen	ted		
	Source of Heating			Gas R-22			
	Refrigerant Type						
	Deficiency				encies recorded		
	Instance			Roof	G 1 15		
	Instance Condition				en Good and Fa	ır	
	Instance Quantity			7			
	Instance Quantity Uom			EACH			
	Manufacturer			Trane			
	EquipmentId			ACCU-3, ACCU-9	ACCU-4, ACC	CU-5, ACCU-6,	ACCU-7, ACCU-8,
	Capacity/Size Quantity			5			
	Capacity/Size UOM			Tons			
	Source of Capacity/Siz	e		Documen	ted		
	Installation Year			2013			
	Source of Installation Y	'ear		Documen	ted		
	Source of Heating			Gas			
	Refrigerant Type			R-22			

Building Condition Assessment Survey 2023-2024

Mechanical Inspection R101

unicui Inspection		KIUI
uestion	Response	
AIR CONDITIONING		
Packaged / Rooftop Unit		
Deficiency	No deficiencies recorded	
Packaged Terminal A/C	Does not exist	
Refrigerant Leak Detection System	Does not exist	
Refrigerant Piping	Does not exist	
Return Fan	Does not exist	
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist	
CLIMATE CONTROL SYSTEM	Inspected	
BMS	Inspected	
Instance	Throughout	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Building Area Covered by Operational System	81-100%	
Installation Year	2020	
Source of Installation Year	Documented	
Deficiency	DEFECTIVE LOCAL CONTROL PANEL	
Deficiency Location/Instance	Custodian's Office	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Pneumatic System	Does not exist	
Hybrid System	Does not exist	
Electric System	Does not exist	
COMPACTOR	Does not exist	
CONVEYING	Inspected	
Dumbwaiter	Does not exist	
Elevator	Inspected	
Condition	1- Good	
Are all the existing elevators operable?	Yes	
Deficiency	No deficiencies recorded	
Escalator	Does not exist	
Non-auditorium Handicap Lift - Vertical	Does not exist	
Non-auditorium Handicap Lift - Stair	Does not exist	
Ash Hoist	Does not exist	
Sidewalk Elevator	Does not exist	
DOMESTIC WATER SYSTEM	Inspected	
Domestic Cold Water System	Does not exist	
Domestic Hot Water System	Inspected	
Domestic Hot Water Remote Storage Tank	Does not exist	
Domestic Water Heat Exchanger	Does not exist	
Electric Domestic Water Heater	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Gas Fired Domestic Water Heater	Does not exist	
Oil Fired Domestic Water Heater	Does not exist	
Heat Pump Domestic Water Heater	Does not exist	
Domestic Water Distribution Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Delicities	1 to deliterations recorded	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection R101

chanical Inspection		KIUI
Question	Response	
DRAIN/WASTE/VENT AND STORM SYSTEM		
Interior Storm Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not exist	
Sump Pump	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
<u>-</u>		
Lavatory/Sink	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Does not exist	
Toilet	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Inspected	
Gas Distribution Piping	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Does not exist	
Gas Meter Room Vent	Does not exist	
Gas Pressure Booster	Does not exist	
CO/Gas Leak Detection	Does not exist	
HEATING	Inspected	
Heating Coil In Ductwork	Does not exist	
Hydronic Heating	Inspected	
Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries	Inspected	
Condition	1- Good	
Deficiency	PUMP:DEFECTIVE	
Deficiency Deficiency Location/Instance	PUMP:DEFECTIVE Boiler Room	
Deficiency Location/Instance Deficiency Quantity		
Deficiency Qualitity	1	

Building Condition Assessment Survey 2023-2024

Question	Response	
HEATING		
Hydronic Heating		
Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries		
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Backflow Preventer	Does not exist	
Hot Water Heat Exchanger	Does not exist	
Radiator/Convector/Fin Tube	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Steam Heating	Does not exist	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
HEATING PLANT	Inspected	
Instance on 2nd Floor	Inspected	
Is there a water meter on the boiler make-up water piping?	No	
Burner Manufacturer	N/A	
Burner Model	N/A	
Burner Type	N/A	
Heating Plant Oil Number	N/A	
Boiler Auxiliaries		
Instance on 2nd Floor	Inspected	
Boiler Auxiliary Piping		
Instance on 2nd Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on 2nd Floor	Inspected	
Instance Condition	1- Good	

Boiler Feedwater System		
Instance on 2nd Floor	Does not exist	
Boiler Feedwater Treatment(Automatic)		
Instance on 2nd Floor	Does not exist	
Boiler Flue Exhaust		
Instance on 2nd Floor	Does not exist	
Boiler Make-up Water Backflow Preventer		
Instance on 2nd Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Boiler Room Steam And Condensate Piping		
Instance on 2nd Floor	Does not exist	
Boiler Safety Valve		
Instance on 2nd Floor	Does not exist	
Boiler System		
Instance on 2nd Floor	Inspected	
Coal-fired Boiler		
Instance on 2nd Floor	Does not exist	
Hot Water Boiler		
Instance on 2nd Floor	Does not exist	
rtners Version 2.0 (P)	Page 4 of 6	Print Date: 8/8/202

Building Condition Assessment Survey 2023-2024

estion		Response	
	G PLANT		
Boiler S			
	ılar Boiler		
	Instance on 2nd Floor	Inspected	
	Instance on 2nd Floor	Inspected	
	Instance	Boiler Room	
	Instance Condition	1- Good	
	Instance Quantity	223	
	Instance Quantity Uom	MBH NET	
	Manufacturer	Lochinvar	
	Manufacturer EquipmentId	N/A	
	Capacity/Size Quantity	256	
	Capacity/Size UOM	MBH Gross	
	Source of Capacity/Size	Documented	
	Installation Year	2020	
	Source of Installation Year	Documented	
	Deficiency	No deficiencies recorded	
Stean	n Boiler		
	Instance on 2nd Floor	Does not exist	
Fuel Sy	vstem		
•	Instance on 2nd Floor	Does not exist	
Inclosed	IDF Room	Does not exist	
KITCHE		Inspected	
XIICHE	Instance on 2nd Floor	Inspected	
CO Det		inspected	
CO Dei	Instance on 2nd Floor	Not required	
C C		Not required	
Gas Sys	Instance on 2nd Floor	Does not exist	
Grease		Does not exist	
Grease	Instance on 2nd Floor	Inspected	
	Instance Condition	1- Good	
	Deficiency	No deficiencies recorded	
	Deliciency	No deficiencies recorded	
Hood	Instance on 2nd Floor	Inquested	
	Instance Condition	Inspected 1- Good	
		No deficiencies recorded	
	Deficiency	No deficiencies recorded	
Hood E	Exhaust Ductwork Instance on 2nd Floor	Inquested	
		Inspected 1- Good	
	Instance Condition	No deficiencies recorded	
	Deficiency	ivo deliciencies recorded	
Hood E	Exhaust Fan	Towns do 1	
	Instance on 2nd Floor	Inspected	
	Instance Condition	1- Good	
	Deficiency	No deficiencies recorded	
Hood F	Fire Suppression System		
	Instance on 2nd Floor	Does not exist	
Hot Wa	ater Temperature Booster		
	Instance on 2nd Floor	Does not exist	
Kitcher			
	Instance on 2nd Floor	Inspected	
	Instance Condition	1- Good	
	Deficiency	No deficiencies recorded	

Inspected

Instance on Room 204

Building Condition Assessment Survey 2023-2024

Mechanical Inspection R101

uestion	Response
MDF Room	
Dedicated A/C Equipment	
Instance on Room 204	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected
Dry Sprinkler Alarm Valve Assembly	Does not exist
Wet Sprinkler Alarm Valve Assembly	Does not exist
Fire Booster Pump Assembly	Does not exist
Roof Tank	Does not exist
Siamese Connection	Does not exist
Sprinkler Head	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Sprinkler Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Standpipe System	Inspected
Hose Valve Assembly	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Piping	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Water Gong	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Is the building Mechanically ventilated?	Yes
Exhaust Fan	Inspected
Condition	1- Good
Approximate Total # of Fans	1-25
Deficiency	No deficiencies recorded
Heating And Ventilating Unit	Does not exist
Metal Ductwork	Inspected
Condition	1- Good
Are there any uninsulated ductwork by design in Mechanical rooms?	No
Are there chain operated dampers?	No
Deficiency	No deficiencies recorded
Supply Fan	Does not exist
Unit Ventilator	Does not exist