NYC Department of Education

Building Condition Assessment Survey 2023-2024

| Mechanical Inspection | R461 |
|-----------------------|------|
| | |

| Mechanica | l Inspection | | | | | | | R461 | |
|---|----------------------------|-------------------------------------|-------------|----------------|-------------|----------------|-------|------------------|--|
| Asset: | WAGNI | ER HS AF - STATEN ISLAND, 1200 |) MANOR ROA | D, STATEN ISL | AND, NY, 10 | 314 | | | |
| Inspection | pection Id Inspection Type | | | | Time | Time In | | st Edited | |
| | 4240 MECHA | NICAL | | | 2024- | -03-27 11:45AN | M 20 | 24-04-12 01:50PM | |
| Asset Data | | | | | | | | | |
| Question | | | | Answer | | | | | |
| Have any | Systems/Major | Building Components been upgraded? | | No System | m Upgraded | | | | |
| Are there | fuel tanks? | | | No | | | | | |
| Total # of | water main serv | rice entries to the asset | | 0 | | | | | |
| MERs/Fa | n Rooms Location | ons | | None | | | | | |
| | | Missing or Defective CO Detectors? | | No | | | | | |
| | | structed Sprinkler Heads? | | No | | | | | |
| | | Stop Switches with Missing Hammers? | | No components | | | | | |
| Priority Co. | | | | | | | | | |
| Exist | Priority | Condition | Component | Location | Person(s) | Person(s) | Photo | | |
| Last Year? | Category | Description | Affected | Description | Notified | Title | Image | | |
| No condit | tion recorded | | | | | | | | |
| Inspection | ! | | | | | | | | |
| Question | | | | Response | 2 | | | | |
| Mechanic | cal | | | | | | | | |
| AIR CO | ONDITIONING | ļ | | Does not | exist | | | | |
| CENTRAL ACID WASTE NEUTRALIZING TANK | | | | Does not exist | | | | | |
| CLIMATE CONTROL SYSTEM | | | | Does not exist | | | | | |
| COMP | ACTOR | | | Does not | exist | | | | |
| CONVI | EYING | | | Does not | exist | | | | |
| DOMESTIC WATER SYSTEM | | | | Does not exist | | | | | |
| DRAIN | //WASTE/VEN | Γ AND STORM SYSTEM | | Does not | exist | | | | |
| DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER) | | | | Does not | exist | | | | |
| FIXTU | RES | | | Does not | exist | | | | |
| GAS FI | IRED FURNAC | Œ | | Does not | exist | | | | |
| GAS SI | ERVICE | | | Does not | exist | | | | |
| HEATI | NG | | | Does not | exist | | | | |
| HEATI | NG PLANT | | | Does not | exist | | | | |
| Enclose | ed IDF Room | | | Does not | exist | | | | |
| KITCH | IEN | | | Does not | exist | | | | |
| MDF R | loom | | | Does not | exist | | | | |
| SCIEN | CE DEMO RO | OM | | Does not | exist | | | | |
| | CE LAB | | | Does not | exist | | | | |
| SCIEN | CE PREP ROO | M | | Does not | exist | | | | |
| SPRIN | KLERS, STAN | DPIPE, FIRE SYSTEM | | Does not | exist | | | | |
| | MING POOL | , | | Does not | exist | | | | |
| - | LATION | | | Does not | exist | | | | |
| , 2., 11 | | | | | | | | | |