NYC Department of Education

Building Condition Assessment Survey 2023-2024

Asset:	P.S. 38 TRA	NSPORTABLE - STATEN ISLA	AND, 421 LINC	OLN AVENUE,	STATEN ISL	AND, NY, 10	306	
Inspection	ı Id Inspection Ty	ре			Time	In	Last Edited	
-	4172 MECHANICA	AL			2024	-03-22 09:18AN	A 2024-03-22 10:0	01AM
sset Data								
Question				Answer				
Have any Systems/Major Building Components been upgraded?				Systems:	Electric Dom	estic Water Heat	er	
				Years:	2021			
Are there	fuel tanks?			No				
Total # of water main service entries to the asset				0				
MERs/Fan Rooms Locations				None				
		sing or Defective CO Detectors?		No				
		ted Sprinkler Heads? Switches with Missing Hammers?		No No compo	nents			
riority Co		Switches with Missing Hammers.		Tto compe	ments			
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo	
Last Year?	Category	Description	Affected	Description	Notified	Title	Image	
No condit	ion recorded							
Inspection	!							
Question				Response	;			
Mechanic	cal							
AIR CO	ONDITIONING			Inspected				
Chilled Water System				Does not	exist			
Cond	enser Water Distrib	ution: Piping, Pumps and Auxiliarie	s	Does not	exist			
Cooling Coil in Ductwork				Does not	exist			
Cooling Tower				Does not				
DX Split System				Does not				
Dry Cooler				Does not				
Packaged / Rooftop Unit				Does not of Inspected				
Packaged Terminal A/C Condition				3- Fair				
Condition Deficiency				No deficiencies recorded				
				Does not exist				
Refrigerant Leak Detection System				Does not				
Refrigerant Piping Return Fan				Does not				
CENTRAL ACID WASTE NEUTRALIZING TANK				Does not	exist			
CLIMATE CONTROL SYSTEM				Does not				
COMPACTOR				Does not exist				
CONVEYING				Does not	exist			
DOMESTIC WATER SYSTEM				Inspected				
Domestic Cold Water System				Does not	exist			
Domestic Hot Water System				Inspected				
Don	nestic Hot Water Re	emote Storage Tank		Does not	exist			
Domestic Water Heat Exchanger				Does not	exist			
Electric Domestic Water Heater				Inspected				
Condition				1- Good				
Deficiency				No deficie	encies recorded			
Gas	Fired Domestic Wa	ter Heater		Does not	exist			
Oil Fired Domestic Water Heater				Does not	exist			
Heat Pump Domestic Water Heater				Does not	exist			
Domestic Water Distribution Piping				Inspected				
Condition					en Good and Fa			
	Deficiency			No deficie	encies recorded			
DRAIN	DRAIN/WASTE/VENT AND STORM SYSTEM			Inspected				
	or Storm Piping		· · · · · · · · · · · · · · · · · · ·	Does not	exist			

NYC Department of Education

Building Condition Assessment Survey 2023-2024

Mechanical Inspection R816

chunicui Inspection		Roto
Question	Response	
DRAIN/WASTE/VENT AND STORM SYSTEM		
Sewage/Waste/Vent Piping	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not exist	
Sump Pump	Does not exist	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Does not exist	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
Student	Inspected	
Drinking Fountain	Does not exist	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Does not exist	
Toilet	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Does not exist	
HEATING	Does not exist	
	Does not exist	
HEATING PLANT		
Enclosed IDF Room	Does not exist	
KITCHEN	Does not exist	
MDF Room	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Yes	
Exhaust Fan	Inspected	
Condition	4- Between Fair and Poor	
Approximate Total # of Fans	1-25	
Deficiency	DEFECTIVE/DETERIORATED	
Deficiency Location/Instance	T-1 - Toilet Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	

NYC Department of Education

Building Condition Assessment Survey 2023-2024

Mechanical Inspection R816

estion	Response				
VENTILATION					
Exhaust Fan					
Deficiency	DEFECTIVE				
Deficiency Location/Instance	T-2 - Toilet Room				
Deficiency Quantity	1				
Quantity Uom	EACH				
Potential Action	MAINTENANCE				
Urgency of Action	PRIORITY 3				
Purpose of Action	LEVEL 2				
Violations	No violations recorded				
Heating And Ventilating Unit	Does not exist				
Metal Ductwork	Inspected				
Condition	2- Between Good and Fair				
Are there any uninsulated ductwork by design in Mechanical rooms?	No				
Are there chain operated dampers?	No				
Deficiency	DEFECTIVE REGISTER/DIFFUSER				
Deficiency Location/Instance	T-2 - Toilet Room				
Deficiency Quantity	1				
Quantity Uom	EACH				
Potential Action	MAINTENANCE				
Urgency of Action	PRIORITY 3				
Purpose of Action	LEVEL 2				
Violations	No violations recorded				
Supply Fan	Does not exist				
Unit Ventilator	Does not exist				