NYC Department of Education

Building Condition Assessment Survey 2023-2024

Asset:	P.S. 3 ANNEX 10309	GYM (CYO BLDG) - STATE	EN ISLAND, 65	81 HYLAN BOU	JLEVARD, S	FATEN ISLA	ND, NY,		
Inspection Id	Inspection Type				Time In		Las	Last Edited	
3410	MECHANICAL				2024	-02-22 10:38A	M 202	4-03-17 12:51AM	
set Data									
Question				Answer					
Have any Syst	ems/Major Building	g Components been upgraded?		No System	n Upgraded				
Are there fuel	tanks?			No					
Total # of water	er main service entr	ies to the asset		0					
MERs/Fan Ro	oms Locations			None					
-	_	g or Defective CO Detectors?		No					
	Painted/Obstructed			No					
		vitches with Missing Hammers?		No compo	onents				
iority Condi		G 11.1		·	.	D ()			
	ority tegory	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image		
No condition r		Безегірион	Tillecteu	Description	Trottilea		Image		
	ccorucu								
spection				n					
Question				Response	2				
Mechanical				T , 1					
AIR COND				Inspected					
-	ater System			Does not					
		on: Piping, Pumps and Auxiliarie	·s	Does not					
Cooling C	oil in Ductwork			Does not					
DX Split S				Does not					
Dry Coole				Does not					
	/ Rooftop Unit			Inspected					
_	nstance			Roof					
Ī	nstance Condition			3- Fair					
Ī	nstance Quantity			2					
— Is	nstance Quantity U	om		EACH					
_	Manufacturer			Trane					
	EquipmentId			RTU-1, R	TU-2				
	Capacity/Size Quant	ity		8					
	Capacity/Size UOM			Tons					
<u>S</u>	Source of Capacity/S	Size		Inspector	Estimate				
	nstallation Year			2001					
	ource of Installatio	n Year		Documen	ted				
_	ource of Heating			Gas					
	Refrigerant Type			R-22					
	Deficiency				encies recorded				
	Terminal A/C	g .		Does not					
	nt Leak Detection	System		Does not					
Refrigera Return Fa				Does not					
		UTRALIZING TANK		Does not					
	CONTROL SYST			Does not					
-		L/IVI		Does not					
CONVEYE									
CONVEYI				Does not					
	C WATER SYSTE			Inspected					
	Cold Water System			Does not					
	Hot Water System			Inspected					
Domestic	Water Distribution	ı rıpıng		mspected					

NYC Department of Education

Building Condition Assessment Survey 2023-2024

Mechanical Inspection	R827
-----------------------	------

chanical Inspection		No2/
Question	Response	
DOMESTIC WATER SYSTEM		
Domestic Water Distribution Piping		
Deficiency	No deficiencies recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not exist	
Sump Pump	Does not exist	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Does not exist	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Does not exist	
Toilet	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
i		
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Inspected	
Gas Distribution Piping	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Does not exist	
Gas Meter Room Vent	Does not exist Does not exist	
Gas Pressure Booster CO/Gas Leak Detection	Does not exist Does not exist	
	Does not exist	
HEATING		
HEATING PLANT	Does not exist	
Enclosed IDF Room	Does not exist	
KITCHEN	Does not exist	
MDF Room	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM		
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Yes	
Exhaust Fan	Inspected	
Condition	3- Fair	

NYC Department of Education

Building Condition Assessment Survey 2023-2024

Mechanical Inspection R827

nestion	Response		
VENTILATION			
Exhaust Fan			
Approximate Total # of Fans	1-25		
Deficiency	No deficiencies recorded		
Heating And Ventilating Unit	Does not exist		
Metal Ductwork	Inspected		
Condition	3- Fair		
Are there any uninsulated ductwork by design in Mechanical rooms?	No		
Are there chain operated dampers?	No		
Deficiency	No deficiencies recorded		
Supply Fan	Does not exist		
Unit Ventilator	Does not exist		