

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X101

Asset: I.S. 101 - BRONX, 2750 LAFAYETTE AVENUE, BRONX, NY, 10465

Inspection Id	Inspection Type	Time In	Last Edited
3715	ELECTRICAL	2024-03-05 08:48AM	2024-05-17 02:38PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Security Lights Years: 2023, 2018 Systems: LED Pendant (1st Floor Partial Classrooms) Years: 2023 Systems: Lightning Protection, Gymnasium (Scoreboard), Variable Frequency Drive Years: 2022 Systems: Most Molded Case Circuit Breaker Panel Boards Years: 2021, 2008, 2000 Systems: Partial Service Switch Years: 2018 Systems: Exit Lights (Battery Packs), Exit/Emergency Lights, Interior Lighting, Partial Emergency Lighting (Non-Battery Packs) Years: 2016 Systems: Intrusion Alarm System (Infrared Sensors) Years: 2014 Systems: Auditorium (Theatre Lighting System, Projection System) Years: 2013 Systems: Fire Alarm System Years: 2010 Systems: Science Lab Room 302, Auxiliary Signal/Bell System, Public Address System, Local Sound System Years: 2009 Systems: Emergency Light/Exit Light Panel Years: 2000 Systems: Intrusion Alarm System Years: 1998
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Fire Alarm System - Defective	N/A	Fire Alarm System - Main Panel	Main Entrance Lobby	Juan Guzman	Fireman	No Photo Taken

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X101

Question	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X101

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist
Local Sound System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on Basement	Does not exist
Theater Lighting System	
Instance on Basement	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Lighting Fixture - Incandescent	
Lighting Fixture - LED	
Pendant Mounted	
Condition	1- Good
Deficiency	No deficiencies recorded
Surface Mounted	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
COMPUTER LAB	
GYMNASIUM	
Instance on 1st Floor	Inspected
Lighting	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X101

Question	Response
GYMNASIUM	
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Scoreboard	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Does not exist
KITCHEN	Inspected
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Does not exist
Surface Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Basement	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X101

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - LED	
Instance on Basement	Does not exist
LIBRARY	Inspected
Instance on Room 128	Inspected
Lighting	
Instance on Room 128	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 128	Inspected
Pendant Mounted	
Instance on Room 128	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 128	Does not exist
Recessed Mounted	
Instance on Room 128	Does not exist
Lighting Fixture - HID	
Instance on Room 128	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 128	Does not exist
Lighting Fixture - LED	
Instance on Room 128	Does not exist
Raceway With Receptacles	
Instance on Room 128	Does not exist
Projection System	
Instance on Room 128	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Inspected
Instance on Room B42	Inspected
Lighting	
Instance on Room B42	Inspected
Lighting Fixture - Fluorescent	
Instance on Room B42	Does not exist
Lighting Fixture - HID	
Instance on Room B42	Does not exist
Lighting Fixture - Incandescent	
Instance on Room B42	Does not exist
Lighting Fixture - LED	
Instance on Room B42	Inspected
Pendant Mounted	
Instance on Room B42	Does not exist
Surface Mounted	
Instance on Room B42	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X101

Question	Response
MULTIPURPOSE ROOM	
Lighting	
Lighting Fixture - LED	
Recessed Mounted	
Instance on Room B42	Does not exist
Local Sound System	
Instance on Room B42	Does not exist
Projection System	
Instance on Room B42	Does not exist
Theater Lighting System	
Instance on Room B42	Does not exist
SCIENCE DEMO ROOM	
	Does not exist
SCIENCE LAB	
Instance on Room 302	Inspected
Power Panel?	Yes
Alternative Use	No
Lighting	
Instance on Room 302	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 302	Inspected
Pendant Mounted	
Instance on Room 302	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 302	Does not exist
Recessed Mounted	
Instance on Room 302	Does not exist
Lighting Fixture - HID	
Instance on Room 302	Inspected
Pendant Mounted	
Instance on Room 302	Does not exist
Surface Mounted	
Instance on Room 302	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on Room 302	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 302	Does not exist
Lighting Fixture - LED	
Instance on Room 302	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 302	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 302	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 302	Inspected
Instructor Unit	
Instance on Room 302	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X101

Question	Response
SCIENCE LAB	
Power Supply	
Instructor Unit	
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 302	Does not exist
Student Unit	
Instance on Room 302	Does not exist
Projection System	
Instance on Room 302	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
SCIENCE PREP ROOM	
Instance on Room 320	Inspected
Power Panel?	No
Alternative Use	Yes
Lighting	
Instance on Room 320	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 320	Inspected
Pendant Mounted	
Instance on Room 320	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 320	Does not exist
Recessed Mounted	
Instance on Room 320	Does not exist
Lighting Fixture - HID	
Instance on Room 320	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 320	Does not exist
Lighting Fixture - LED	
Instance on Room 320	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 320	Does not exist
Emergency Shut-Off Power	
Instance on Room 320	Does not exist
Power Supply	
Instance on Room 320	Does not exist
SWIMMING POOL	
TOILET ROOM - STAFF	
Inspected	Inspected
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Does not exist	Does not exist
Surface Mounted	
Inspected	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Does not exist	Does not exist
Lighting Fixture - HID	
Does not exist	Does not exist
Lighting Fixture - Incandescent	
Does not exist	Does not exist
Lighting Fixture - LED	
Does not exist	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X101

Question	Response
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Gymnasium
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X101

Question	Response
FIRE ALARM SYSTEM	
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
Model	EST 2
EquipmentId	Fire Alarm Control Panel
Installation Year	2010
Source of Installation Year	Documented
Deficiency	PANEL DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	12124984J
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X101

Question	Response
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Rooms B37, B6
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 135
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland MPA 250
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Under construction
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	3- Fair
Instance Quantity	1

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X101

Question	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	1998
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Meter Room B37
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Square D
EquipmentId	Fire Pump Disconnect
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2018
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Meter Room B37
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Empire Switchboard
EquipmentId	Heating Equipment - B
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1957
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room B37
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X101

Question	Response
SERVICE SWITCH	
Instance	Electrical Meter Room B37
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Empire Switchboard
EquipmentId	Switchboard No.1 Section A
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1957
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room B37
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Meter Room B37
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Empire Switchboard
EquipmentId	Switchboard No.1 Section B
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1957
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room B37
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Meter Room B37
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Empire Switchboard
EquipmentId	Switchboard No.2 Section A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1957
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room B37
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X101

Question	Response
SERVICE SWITCH	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Meter Room B37
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Empire Switchboard
EquipmentId	Switchboard No.2 Section B
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1957
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room B37
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	1
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Instance	Electrical Meter Room B37
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Empire Switchboard
EquipmentId	Sec A
Capacity/Size Quantity	625
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1957
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room B37
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Meter Room B37
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Empire Switchboard
EquipmentId	Sec B
Capacity/Size Quantity	625
Capacity/Size UOM	Amps Total

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X101

Question	Response
SWITCHBOARD	
Molded Case Circuit Breaker Type	
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1957
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Meter Room B37
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B6
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Empire Switchboard
EquipmentId	Sec A
Capacity/Size Quantity	625
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1957
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B6
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B6
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Empire Switchboard
EquipmentId	Sec B
Capacity/Size Quantity	625
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1957
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B6
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X101

Question	Response
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist