

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X177**

**Asset: THE NORWOOD EAST CAMPUS - BRONX, 3177 WEBSTER AVENUE, BRONX, NY, 10467**

Inspection Id	Inspection Type	Time In	Last Edited
4117	ELECTRICAL	2024-03-21 09:08AM	2024-05-20 01:40PM


**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: All Systems and Components Years: 2014
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	No
Which rooms or areas have non-operational dedicated intercoms?	Rooms 202, 302, 402, 502

**Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Fire Alarm System - Components Not Operational	N/A	Fire Alarm System - Fan Shutdown Control	RTU #6	Hemanlall Mangroo	Fireman	No Photo Taken
Yes	Lightning Protection - Defective	N/A	Lightning Protection	Roof - Exhaust Fans	Hemanlall Mangroo	Fireman	

**Inspection**

Question	Response
<b>Electrical</b>	
<b>ATHLETIC FIELD</b>	Does not exist
<b>AUDITORIUM</b>	Does not exist
<b>CAFETERIA</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting</b>	
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Surface Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - LED</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X177**

Question	Response
<b>CAFETERIA</b>	
<b>Lighting</b>	
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not exist
<b>Local Sound System</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on 1st Floor	Does not exist
<b>Theater Lighting System</b>	
Instance on 1st Floor	Does not exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	
Does a Chandelier Exist?	No
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Lighting Fixture - LED</b>	
<b>Pendant Mounted</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
<b>Recessed Mounted</b>	
<b>COMPUTER LAB</b>	
<b>GYMNASIUM</b>	
Instance on 2nd Floor	Inspected
Instance on 4th Floor	Inspected
<b>Lighting</b>	
Instance on 2nd Floor	Inspected
Instance on 4th Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 2nd Floor	Inspected
Instance on 4th Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 4th Floor	Does not exist
<b>Surface Mounted</b>	
Instance on 2nd Floor	Does not exist
Instance on 4th Floor	Does not exist
<b>Recessed Mounted</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X177**

Question	Response
<b>GYMNASIUM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	
Instance on 2nd Floor	Does not exist
Instance on 4th Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 2nd Floor	Does not exist
Instance on 4th Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 2nd Floor	Does not exist
Instance on 4th Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 2nd Floor	Inspected
Instance on 4th Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 2nd Floor	Does not exist
Instance on 4th Floor	Does not exist
<b>Surface Mounted</b>	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 4th Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on 2nd Floor	Does not exist
Instance on 4th Floor	Does not exist
<b>Local Sound System</b>	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance on 4th Floor	Inspected
Instance Condition	3- Fair
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on 2nd Floor	Inspected
Instance Condition	5- Poor
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	VIDEO PROJECTOR IS NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 4th Floor	Does not exist
<b>Scoreboard</b>	
Instance on 2nd Floor	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X177**

Question	Response
<b>GYMNASIUM</b>	
<b>Scoreboard</b>	
Instance on 4th Floor	Does not exist
<b>Theater Lighting System</b>	
Instance on 2nd Floor	Inspected
Instance on 4th Floor	Does not exist
<b>Dimming System</b>	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting</b>	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>KITCHEN</b>	
Instance on 1st Floor	Inspected
<b>Lighting</b>	
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Surface Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Recessed Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not exist
<b>LIBRARY</b>	
Instance on Room 215	Inspected
<b>Lighting</b>	
Instance on Room 215	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 215	Inspected
<b>Pendant Mounted</b>	
Instance on Room 215	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 215	Does not exist
<b>Recessed Mounted</b>	
Instance on Room 215	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 215	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 215	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 215	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X177**

Question	Response
<b>LIBRARY</b>	
<b>Lighting</b>	
<b>Lighting Fixture - LED</b>	
<b>Raceway With Receptacles</b>	
Instance on Room 215	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on Room 215	Does not exist
<b>LOCKER ROOM</b>	
Instance on Rooms 405A - Boys, 405B - Girls	Inspected
Alternative Use	Yes
<b>Lighting</b>	
Instance on Rooms 405A - Boys, 405B - Girls	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Rooms 405A - Boys, 405B - Girls	Inspected
<b>Pendant Mounted</b>	
Instance on Rooms 405A - Boys, 405B - Girls	Does not exist
<b>Surface Mounted</b>	
Instance on Rooms 405A - Boys, 405B - Girls	Does not exist
<b>Recessed Mounted</b>	
Instance on Rooms 405A - Boys, 405B - Girls	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Rooms 405A - Boys, 405B - Girls	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Rooms 405A - Boys, 405B - Girls	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Rooms 405A - Boys, 405B - Girls	Does not exist
<b>MULTIPURPOSE ROOM</b>	
	Does not exist
<b>SCIENCE DEMO ROOM</b>	
	Does not exist
<b>SCIENCE LAB</b>	
Instance on Room 520	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room 524	Inspected
Power Panel?	Yes
Alternative Use	No
<b>Lighting</b>	
Instance on Room 520	Inspected
Instance on Room 524	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 520	Inspected
Instance on Room 524	Inspected
<b>Pendant Mounted</b>	
Instance on Room 520	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 524	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X177**

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Instance on Room 520	Does not exist
Instance on Room 524	Does not exist
<b>Recessed Mounted</b>	
Instance on Room 520	Does not exist
Instance on Room 524	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 520	Does not exist
Instance on Room 524	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 520	Inspected
Instance on Room 524	Does not exist
<b>Pendant Mounted</b>	
Instance on Room 520	Does not exist
<b>Surface Mounted</b>	
Instance on Room 520	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room 520	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 520	Does not exist
Instance on Room 524	Does not exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 520	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 524	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room 520	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 524	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	
Instance on Room 520	Does not exist
Instance on Room 524	Does not exist
<b>Projection System</b>	
Instance on Room 520	Does not exist
Instance on Room 524	Does not exist
<b>SCIENCE PREP ROOM</b>	
Instance on Room 522	Inspected
Power Panel?	No
Alternative Use	No
<b>Lighting</b>	
Instance on Room 522	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 522	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X177**

Question	Response
<b>SCIENCE PREP ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Instance on Room 522	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 522	Does not exist
<b>Recessed Mounted</b>	
Instance on Room 522	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 522	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 522	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 522	Does not exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 522	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room 522	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	
Instance on Room 522	Does not exist
<b>SWIMMING POOL</b>	Does not exist
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Does not exist	
<b>Surface Mounted</b>	
Does not exist	
<b>Recessed Mounted</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Does not exist	
<b>Lighting Fixture - Incandescent</b>	
Does not exist	
<b>Lighting Fixture - LED</b>	
Does not exist	
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Does not exist	
<b>Surface Mounted</b>	
Does not exist	
<b>Recessed Mounted</b>	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Does not exist	
<b>Lighting Fixture - Incandescent</b>	
Does not exist	
<b>Lighting Fixture - LED</b>	
Does not exist	
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X177**

<b>Question</b>	<b>Response</b>
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not exist
<b>EMERGENCY GENERATOR SET</b>	Inspected
<b>Automatic Transfer Switch (ATS)</b>	Inspected
Instance	A.T.S. Room 104
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	GE Zenith Controls
EquipmentId	ATS #1
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	A.T.S. Room 104
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	GE Zenith Controls
EquipmentId	ERP - Generator
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	A.T.S. Room 104
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	GE Zenith Controls
EquipmentId	Fire Alarm Automatic Transfer Switch
Capacity/Size Quantity	40
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Fire Pump Room 130
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Tornatech
EquipmentId	Fire Pump Power Transfer Switch
Capacity/Size Quantity	60
Capacity/Size UOM	HP
Source of Capacity/Size	Nameplate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Battery Charger</b>	Inspected
Instance	Roof - Generator Enclosure
Instance Condition	2- Between Good and Fair
Instance Quantity	1



**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X177**

Question	Response
<b>EMERGENCY GENERATOR SET</b>	
<b>Battery Charger</b>	
Instance Quantity Uom	EACH
Manufacturer	SENS
EquipmentId	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size 2 Quantity	24
Capacity/Size 2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Emergency Distribution Board</b>	Inspected
Number of Spares	3
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	A.T.S. Room 104
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	N/A
Capacity/Size Quantity	958
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Molded Case Circuit Breaker Type</b>	Does not exist
<b>Diesel</b>	Inspected
Instance	Roof - Generator Enclosure
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Caterpillar
EquipmentId	Emergency Generator
Capacity/Size Quantity	345
Capacity/Size UOM	kVA
Capacity/Size 2 Quantity	276
Capacity/Size 2 UOM	kW
Capacity/Size 3 Quantity	958
Capacity/Size 3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Natural Gas</b>	Does not exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Does not exist
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Does not exist
<b>Non Battery Pack</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X177**

Question	Response
<b>EXIT LIGHT</b>	
<b>Battery Pack</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Does not exist
<b>EXIT/EMERGENCY LIGHT</b>	Does not exist
<b>FIRE ALARM SYSTEM</b>	
<b>Bell/Horn</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	CONTROL NOT OPERATIONAL
Deficiency Location/Instance	RTU #6
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	12042170L
<b>Duct Smoke Detector</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Area Smoke Detector</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Heat Detector</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Magnetic Door Holder/Contactor</b>	Does not exist
<b>Fused Cutout Panel</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Does not exist
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Does not exist
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards System Technology
Model	EST 3

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X177**

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Main Panel</b>	
<b>Fire Alarm Control Panel (Electronic)</b>	
EquipmentId	Fire Alarm Control Panel
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	
	Does not exist
<b>Sub-Panel</b>	
	Inspected
<b>Bell At Panel</b>	
	Does not exist
<b>Fire Alarm Control Panel (Electronic)</b>	
	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards System Technology
Model	EST 3
EquipmentId	Fire Alarm Horn Strobe Panel
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	
	Does not exist
<b>Remote Annunciator</b>	
	Inspected
<b>Display Monitor</b>	
	Does not exist
<b>Panel</b>	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Printer</b>	
	Inspected
Condition	5- Poor
Deficiency	PRINTER NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Punch Register</b>	
	Does not exist
<b>Sprinkler Flow/Air Pressure Switch</b>	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Tamper Flow Switch/Chain</b>	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>INTERCOM SYSTEM</b>	
	Inspected
<b>Elevator</b>	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Holding Area</b>	
	Does not exist
<b>LAN</b>	
	Inspected
<b>Local Distribution Frame (I/LDF)</b>	
	Inspected
Condition	2- Between Good and Fair

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X177**

<b>Question</b>	<b>Response</b>
<b>LAN</b>	
<b>Local Distribution Frame (I/LDF)</b>	
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	LIGHTNING AIR TERMINAL (ROD) DEFECTIVE
Deficiency Location/Instance	Roof - Exhaust Fan
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
<b>MOTOR CONTROLLER</b>	Inspected
<b>MOTOR CONTROL CENTER</b>	Does not exist
<b>MOTOR STARTER/CONTACTOR</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Variable Frequency Drive</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Does not exist
<b>Fused Knife Switch Type</b>	Does not exist
<b>Fused Toggle Switch Type</b>	Does not exist
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Instance	Telecom Room 313
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Biamp MPA250
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>SECURITY</b>	Inspected
<b>IPDVS/CCTV System</b>	Inspected
Condition	2- Between Good and Fair
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Intrusion Alarm System</b>	Inspected
<b>Central Control Panel</b>	Inspected
Instance	Custodian's Office - Room 126
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BP
Installation Year	2014

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X177**

Question	Response
<b>SECURITY</b>	
<b>Intrusion Alarm System</b>	
<b>Central Control Panel</b>	
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>Panic Switch</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>Remote Annunciator</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>Siren/Strobe</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>Lighting - Security</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
<b>SERVICE SWITCH</b>	
Instance	Inspected
Instance Condition	Switchgear Room 102
Instance Quantity	2- Between Good and Fair
Instance Quantity Uom	1
Manufacturer	EACH
EquipmentId	Electrotech
Capacity/Size Quantity	Fire Pump
Capacity/Size UOM	1200
Source of Capacity/Size	Amps
Installation Year	Nameplate
Source of Installation Year	2014
Deficiency	Documented
Instance	No deficiencies recorded
Instance Condition	Switchgear Room 102
Instance Quantity	2- Between Good and Fair
Instance Quantity Uom	1
Manufacturer	EACH
EquipmentId	Electrotech
Capacity/Size Quantity	Main Disconnect
Capacity/Size UOM	2500
Source of Capacity/Size	Amps
Installation Year	Nameplate
Source of Installation Year	2014
Deficiency	Documented
Instance	No deficiencies recorded
Instance Condition	Switchgear Room 102
Instance Quantity	2- Between Good and Fair
Instance Quantity Uom	1
Manufacturer	EACH
EquipmentId	Electrotech
Capacity/Size Quantity	MRPP
Capacity/Size UOM	3000
Source of Capacity/Size	Amps
Installation Year	Nameplate
Deficiency	2014

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X177**

<b>Question</b>	<b>Response</b>
<b>SERVICE SWITCH</b>	
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>SWITCHBOARD</b>	
Number of Spares	7
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Mechanical Room R01A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	N/A
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Switchgear Room 102
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	N/A
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	3
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not exist
<b>Molded Case Circuit Breaker Type</b>	Does not exist
<b>TELEPHONE SYSTEM</b>	
<b>PBX/Intercom</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	Does not exist