NYC Department of Education

Building Condition Assessment Survey 2023-2024

Electrical Inspection

T., ·*						í	L 4 E P/ - 1
Inspectio					Time l		Last Edited
	1991 ELECTRICAL				2023-	12-29 07:40AN	4 2024-01-19 11:08AN
set Data							
Question	1			Answer			
Have any	/ Systems/Major Building	Components been upgraded?		Systems:		Systems and Co	omponents
				Years:	2016		
Type of S				Below Gro	ound		
	eractive Whiteboard (IWE	/		Yes			
	netration In Electrical Ro			No			
Question		IN FIRE RESCUE AREAS		D	esponse		
Are the		tance Areas, Fire Rescue Areas, ar	nd/or Holding Room		lo		
iority Co	ondition						
xist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
ast Year?	Category	Description	Affected	Description	Notified	Title	Image
No condi	tion recorded						
nspection	n						
Question	1			Response			
Electrica	al						
ATHL	ETIC FIELD			Does not e	xist		
AUDI	FORIUM			Does not e	xist		
CAFE	TERIA			Does not e	xist		
CLASS	SROOM/CORRIDOR/A	ADMINISTRATIVE SPACE		Inspected			
Light				Inspected			
0	es a Chandelier Exist?			No			
Lig	ghting Fixture - Fluoresc	ent		Does not e	xist		
Lig	ghting Fixture - HID			Does not e	xist		
Lig	ghting Fixture - Incandes	scent		Does not e	xist		
Lig	ghting Fixture - LED			Inspected			
P	endant Mounted			Does not e	xist		
S	urface Mounted			Inspected			
	Condition				n Good and Fair	•	
_	Deficiency			No deficie	ncies recorded		
R	Recessed Mounted			Inspected			
	Condition			2- Betwee	n Good and Fair	•	
	Deficiency			No deficie	ncies recorded		
COMP	PUTER LAB			Does not e	xist		
GYMN	NASIUM			Does not e	xist		
KITCI	HEN			Does not e	xist		
LIBRA	ARY			Inspected			
	Instance on Room 11	7		Inspected			
Light	ting						
-	Instance on Room 11	7		Inspected			
Lig	ghting Fixture - Fluoresc	ent					
	Instance on Room 11	7		Does not e	xist		
Lig	ghting Fixture - HID						
_	Instance on Room 11	7		Does not e	xist		
Lig	ghting Fixture - Incandes	scent					
	Instance on Room 11	7		Does not e	xist		
Lig	ghting Fixture - LED						
	Instance on Room 11	7		Inspected			

NYC Department of Education

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response
LIBRARY	
Lighting	
Lighting Fixture - LED	-
Pendant Mounted	
Instance on Room 117	Does not exist
Surface Mounted	
Instance on Room 117	Does not exist
Recessed Mounted	
Instance on Room 117	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Raceway With Receptacles	
Instance on Room 117	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 117	Does not exist
	Does not exist
LOCKER ROOM	
MULTIPURPOSE ROOM	Inspected
Instance on Room 106	Inspected
Lighting	
Instance on Room 106	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 106	Does not exist
Lighting Fixture - HID	
Instance on Room 106	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 106	Does not exist
Lighting Fixture - LED	
Instance on Room 106	Inspected
Pendant Mounted	
Instance on Room 106	Does not exist
Surface Mounted	
Instance on Room 106	Does not exist
Recessed Mounted	
Instance on Room 106	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Local Sound System	
Instance on Room 106	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2016
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 106	Does not exist

Electrical Inspection

Response Does not exist Inspected Yes No Inspected Does not exist Does not exist Does not exist	
Inspected Inspected Yes No Inspected Does not exist Does not exist	
Inspected Yes No Inspected Does not exist Does not exist	
Yes No Inspected Does not exist Does not exist	
No Inspected Does not exist Does not exist	
Inspected Does not exist Does not exist	
Does not exist Does not exist	
Does not exist Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Inspected	
Does not exist	
Does not exist	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
-	
*	
Yes	
Inspected	
Does not exist	
Does not exist	
Does not exist	
Inspected	
Does not exist	
	Inspected Does not exist Does not exist Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Does not exist Does not exist Inspected Inspected Inspected Inspected Inspected Inspected Does not exist Does not exist Does not exist Does not exist Does not exist Does not exist Does not exist

NYC Department of Education

Building Condition Assessment Survey 2023-2024

Electrical Inspection

	A33
Response	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Inspected	
Inspected	
Does not exist	
Does not exist	
Does not exist	
Inspected	
Does not exist	
Does not exist	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
Does not exist	
Does not exist	
Does not exist	
Inspected	
Does not exist	
Does not exist	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
-	
-	
2- Between Good and Fair No deficiencies recorded Does not exist	
	Inspected 2- Between Good and Fair No deficiencies recorded Does not exist Does not exist Does not exist Does not exist Inspected Inspected Does not exist Does not exist Does not exist Does not exist Does not exist Does not exist Does not exist Inspected Does not exist Inspected 2- Between Good and Fair No deficiencies recorded Inspected Inspected Does not exist Does not

Electrical Inspection

		ЛЭЭ
estion	Response	
IRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST3X	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2016	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer		
Condition	2- Between Good and Fair	

Electrical Inspection

AJ
Response
Does not exist
Inspected
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
Does not exist Does not exist
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
Telecom Room 120
2- Between Good and Fair
1 EACH
Bogen HTA250A
2016
Documented No deficiencies recorded
Inspected
Inspected
2- Between Good and Fair
2016 Documented
No deficiencies recorded
Inspected
Inspected
Custodian's Office
2- Between Good and Fair
1 EACH
EALE
Vista 128BPT
Vista 128BPT 2016
Vista 128BPT 2016 Documented
Vista 128BPT 2016 Documented No deficiencies recorded
Vista 128BPT 2016 Documented No deficiencies recorded Inspected
Vista 128BPT 2016 Documented No deficiencies recorded

Electrical Inspection

Response Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair	
2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected	
2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected	
2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected	
No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected Inspected Inspected Inspected	
Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected Inspected	
2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected Inspe	
No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected Inspected Inspected Inspected No deficiencies recorded Inspected	
Inspected 2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected	
2- Between Good and Fair No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected	
No deficiencies recorded Inspected 2- Between Good and Fair No deficiencies recorded Inspected	
Inspected 2- Between Good and Fair No deficiencies recorded Inspected	
2- Between Good and Fair No deficiencies recorded Inspected	
No deficiencies recorded Inspected	
Inspected	
•	
Basement - Electric Meter Room	
2- Between Good and Fair	
1	
EACH	
Square D	
School Panel DP Disc. SW.	
600	
Amps	
Nameplate	
2016	
Documented	
No deficiencies recorded	
Inspected	
3	
Does not exist	
1	
2- Between Good and Fair	
1	
EACH	
Square D	
DP	
600	
Amps Total	
1	
-	
No deficiencies recorded	
Inspected	
2 Between Good and Fair	
	-
	Does not exist Inspected Electrical Room 126 2- Between Good and Fair 1 EACH Square D DP 600 Amps Total 1 Section(s) Nameplate 2016 Documented No deficiencies recorded Inspected 2. Between Good and Fair No deficiencies recorded