

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X400**

**Asset:** MORRIS HS - BRONX, 1110 BOSTON ROAD, BRONX, NY, 10456

Inspection Id	Inspection Type	Time In	Last Edited
4701	ELECTRICAL	2024-04-11 10:04AM	2024-05-17 10:47AM

**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Elevator (Intercom), Partial LAN (IDF). Years: 2023 Systems: 5th Floor Gymnasium Scoreboard, LED Lighting (Recessed in Room 323, Pendant in Rooms 102, 103, and New Student Toilet Room 104) Years: 2022 Systems: Interior Retrofitted Fluorescent Lighting (Except Corridors, Stairways, 5th Floor Locker Room), Library, IPDVS/CCTV System, Partial Exit Lights (Battery Pack). Years: 2019 Systems: Fire Alarm System Years: 2018 Systems: Intrusion Alarm System (Panic Switch) Years: 2017 Systems: LED Lighting (Gymnasiums) Years: 2015 Systems: Most Variable Frequency Drives Years: 2014 Systems: Telephone System Years: 2013 Systems: Molded Case Circuit Breaker Panel Board Years: 2011, 2008, 1993 Systems: Public Address System, Local Sound System Years: 2009 Systems: Security Lights Years: 2008 Systems: 5th Floor Locker Rooms Years: 2004 Systems: Intrusion Alarm System (Except Panic Switch), Auditorium (Theater Lighting System) Years: 2003 Systems: Emergency Generator Set, Switchboard, Corridors and Stairways Decorative Lighting, Service Switch Years: 1993 Below Ground
Type of Service	
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

**Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Water Leaks onto Electrical Equipment	N/A	Lighting Fixture	2nd Floor Mechanical Room near Stair H, Room 511	Luis Rodrigues	Fireman	No Photo Taken

**NYC Department of Education**  
**Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X400**

No	Intercom - Not Connected to Remote Monitoring Station	N/A	Intercom System - Elevator	Elevator ID : 2P88, 2P89	Luis Rodrigues	Fireman	No Photo Taken
----	---	-----	----------------------------------	-----------------------------	-------------------	---------	----------------

**Inspection**

Question	Response
<b>Electrical</b>	
<b>ATHLETIC FIELD</b>	Does not exist
<b>AUDITORIUM</b>	Inspected
Instance on 1st Floor	Inspected
<b>House Lighting</b>	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	Yes
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Surface Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	40
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not exist
<b>Local Sound System</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X400**

Question	Response
<b>AUDITORIUM</b>	
<b>Projection System</b>	
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	
Instance on 1st Floor	Inspected
<b>Dimming System</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>CAFETERIA</b>	
Instance on Basement - Staff	Inspected
Instance on Basement - Students	Inspected
<b>Lighting</b>	
Instance on Basement - Staff	Inspected
Instance on Basement - Students	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement - Staff	Inspected
Instance on Basement - Students	Inspected
<b>Pendant Mounted</b>	
Instance on Basement - Staff	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Basement - Students	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Basement - Staff	Does not exist
Instance on Basement - Students	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Basement - Staff	Does not exist
Instance on Basement - Students	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Basement - Staff	Does not exist
Instance on Basement - Students	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement - Staff	Does not exist
Instance on Basement - Students	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Basement - Staff	Does not exist
Instance on Basement - Students	Does not exist
<b>Local Sound System</b>	
Instance on Basement - Staff	Does not exist
Instance on Basement - Students	Inspected
Instance Condition	3- Fair
Installation Year	2009

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X400**

Question	Response
<b>CAFETERIA</b>	
<b>Local Sound System</b>	
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on Basement - Staff	Does not exist
Instance on Basement - Students	Does not exist
<b>Theater Lighting System</b>	
Instance on Basement - Staff	Does not exist
Instance on Basement - Students	Does not exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	Inspected
Does a Chandelier Exist?	Yes
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
	Does not exist
<b>Lighting Fixture - Incandescent</b>	
	Inspected
<b>Pendant Mounted</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
	Does not exist
<b>Lighting Fixture - LED</b>	
	Inspected
<b>Pendant Mounted</b>	
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
	Does not exist
<b>Recessed Mounted</b>	
Condition	1- Good
Deficiency	No deficiencies recorded
<b>COMPUTER LAB</b>	
	Inspected
Instance on Room 007	Inspected
Power Panel?	No
<b>Lighting</b>	
Instance on Room 007	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 007	Inspected
<b>Pendant Mounted</b>	
Instance on Room 007	Does not exist
<b>Surface Mounted</b>	
Instance on Room 007	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X400**

Question	Response
<b>COMPUTER LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	
Instance on Room 007	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 007	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 007	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 007	Does not exist
<b>Raceway With Receptacles</b>	
Instance on Room 007	Does not exist
<b>GYMNASIUM</b>	
Instance on 1st Floor	Inspected
Instance on 5th Floor	Inspected
<b>Lighting</b>	
Instance on 1st Floor	Inspected
Instance on 5th Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Does not exist
Instance on 5th Floor	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not exist
Instance on 5th Floor	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not exist
Instance on 5th Floor	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Inspected
Instance on 5th Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 1st Floor	Does not exist
Instance on 5th Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Surface Mounted</b>	
Instance on 1st Floor	Does not exist
Instance on 5th Floor	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Recessed Mounted</b>	

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X400**

Question	Response
<b>GYMNASIUM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - LED</b>	
<b>Recessed Mounted</b>	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 5th Floor	Does not exist
<b>Local Sound System</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance on 5th Floor	Inspected
Instance Condition	3- Fair
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on 1st Floor	Does not exist
Instance on 5th Floor	Does not exist
<b>Scoreboard</b>	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on 5th Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	
Instance on 1st Floor	Does not exist
Instance on 5th Floor	Does not exist
<b>KITCHEN</b>	
Instance on Basement	Inspected
<b>Lighting</b>	
Instance on Basement	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement	Inspected
<b>Pendant Mounted</b>	
Instance on Basement	Does not exist
<b>Surface Mounted</b>	
Instance on Basement	Does not exist
<b>Recessed Mounted</b>	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Basement	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Basement	Does not exist
<b>LIBRARY</b>	
Instance on Room 300	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X400**

Question	Response
<b>LIBRARY</b>	
<b>Lighting</b>	
Instance on Room 300	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 300	Inspected
<b>Pendant Mounted</b>	
Instance on Room 300	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 300	Does not exist
<b>Recessed Mounted</b>	
Instance on Room 300	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 300	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 300	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 300	Inspected
<b>Pendant Mounted</b>	
Instance on Room 300	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 300	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Room 300	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Raceway With Receptacles</b>	
Instance on Room 300	Does not exist
<b>Projection System</b>	
Instance on Room 300	Does not exist
<b>LOCKER ROOM</b>	
Instance on Room 104 - Boys	Inaccessible
Instance on Room 514 - Girls	Inspected
Alternative Use	No
Instance on Room 518 - Boys	Inspected
Alternative Use	No
<b>Lighting</b>	
Instance on Room 514 - Girls	Inspected
Instance on Room 518 - Boys	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 514 - Girls	Inspected
Instance on Room 518 - Boys	Inspected
<b>Pendant Mounted</b>	
Instance on Room 514 - Girls	Does not exist
Instance on Room 518 - Boys	Does not exist
<b>Surface Mounted</b>	
Instance on Room 514 - Girls	Does not exist
Instance on Room 518 - Boys	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X400**

Question	Response
<b>LOCKER ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	
Instance on Room 514 - Girls	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 518 - Boys	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Room 514 - Girls	Does not exist
Instance on Room 518 - Boys	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 514 - Girls	Does not exist
Instance on Room 518 - Boys	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 514 - Girls	Does not exist
Instance on Room 518 - Boys	Does not exist
<b>MULTIPURPOSE ROOM</b>	Does not exist
<b>SCIENCE DEMO ROOM</b>	Inspected
Instance on Room 231, 315, 317	Inspected
Power Panel?	No
Alternative Use	Yes
Instance on Room 227, 229	Inspected
Power Panel?	No
Alternative Use	No
<b>Lighting</b>	
Instance on Room 231, 315, 317	Inspected
Instance on Room 227, 229	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 231, 315, 317	Inspected
Instance on Room 227, 229	Inspected
<b>Pendant Mounted</b>	
Instance on Room 231, 315, 317	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 227, 229	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 231, 315, 317	Does not exist
Instance on Room 227, 229	Does not exist
<b>Recessed Mounted</b>	
Instance on Room 231, 315, 317	Does not exist
Instance on Room 227, 229	Does not exist
<b>Lighting Fixture - HID</b>	
Instance on Room 231, 315, 317	Does not exist
Instance on Room 227, 229	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 231, 315, 317	Does not exist
Instance on Room 227, 229	Does not exist
<b>Lighting Fixture - LED</b>	



**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X400**

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - LED</b>	
Instance on Room 231, 315, 317	Does not exist
Instance on Room 227, 229	Does not exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 231, 315, 317	Does not exist
Instance on Room 227, 229	Does not exist
<b>Emergency Shut-Off Power</b>	
Instance on Room 231, 315, 317	Does not exist
Instance on Room 227, 229	Does not exist
<b>Power Supply</b>	
Instance on Room 231, 315, 317	Inspected
Instance on Room 227, 229	Inspected
<b>Instructor Unit</b>	
Instance on Room 231, 315, 317	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 227, 229	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Room 231, 315, 317	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 227, 229	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on Room 231, 315, 317	Does not exist
Instance on Room 227, 229	Does not exist
<b>SCIENCE LAB</b>	
Instance on Room 121	Inspected
Power Panel?	No
Alternative Use	No
Instance on Room 128	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room 233	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room 415	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room 511	Inspected
Power Panel?	No
Alternative Use	No
Instance on Room 515	Inspected
Power Panel?	Yes
Alternative Use	Yes
<b>Lighting</b>	
Instance on Room 121	Inspected
Instance on Room 128	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X400**

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
Instance on Room 233	Inspected
Instance on Room 415	Inspected
Instance on Room 511	Inspected
Instance on Room 515	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 121	Inspected
Instance on Room 128	Inspected
Instance on Room 233	Inspected
Instance on Room 415	Inspected
Instance on Room 511	Inspected
Instance on Room 515	Inspected
<b>Pendant Mounted</b>	
Instance on Room 121	Does not exist
Instance on Room 128	Does not exist
Instance on Room 233	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 415	Does not exist
Instance on Room 511	Does not exist
Instance on Room 515	Does not exist
<b>Surface Mounted</b>	
Instance on Room 121	Does not exist
Instance on Room 128	Does not exist
Instance on Room 233	Does not exist
Instance on Room 415	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 511	Does not exist
Instance on Room 515	Does not exist
<b>Recessed Mounted</b>	
Instance on Room 121	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 128	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 233	Does not exist
Instance on Room 415	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 511	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 515	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X400**

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - HID</b>	
Instance on Room 121	Does not exist
Instance on Room 128	Does not exist
Instance on Room 233	Does not exist
Instance on Room 415	Does not exist
Instance on Room 511	Does not exist
Instance on Room 515	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 121	Does not exist
Instance on Room 128	Does not exist
Instance on Room 233	Does not exist
Instance on Room 415	Does not exist
Instance on Room 511	Does not exist
Instance on Room 515	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 121	Does not exist
Instance on Room 128	Does not exist
Instance on Room 233	Does not exist
Instance on Room 415	Does not exist
Instance on Room 511	Does not exist
Instance on Room 515	Does not exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 121	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 128	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 233	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 415	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 511	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 515	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room 121	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 128	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 233	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 415	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X400**

<b>Question</b>	<b>Response</b>
<b>SCIENCE LAB</b>	
<b>Emergency Shut-Off Power</b>	
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 511	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 515	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	
Instance on Room 121	Inspected
Instance on Room 128	Inspected
Instance on Room 233	Inspected
Instance on Room 415	Inspected
Instance on Room 511	Inspected
Instance on Room 515	Inspected
<b>Instructor Unit</b>	
Instance on Room 121	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 128	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 233	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 415	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 511	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 515	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Room 121	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 128	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 233	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 415	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 511	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 515	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X400**

Question	Response
<b>SCIENCE LAB</b>	
<b>Power Supply</b>	
<b>Student Unit</b>	
Instance on Room 121	Does not exist
Instance on Room 128	Does not exist
Instance on Room 233	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 415	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 511	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 515	Does not exist
<b>Projection System</b>	
Instance on Room 121	Does not exist
Instance on Room 128	Does not exist
Instance on Room 233	Does not exist
Instance on Room 415	Does not exist
Instance on Room 511	Does not exist
Instance on Room 515	Does not exist
<b>SCIENCE PREP ROOM</b>	
Instance on Room 128A	Inspected
Power Panel?	No
Alternative Use	No
Instance on Room 235	Inspected
Power Panel?	No
Alternative Use	No
Instance on Room 415A	Inspected
Power Panel?	No
Alternative Use	No
Instance on Room 511A	Inspected
Power Panel?	Yes
Alternative Use	No
<b>Lighting</b>	
Instance on Room 128A	Inspected
Instance on Room 235	Inspected
Instance on Room 415A	Inspected
Instance on Room 511A	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 128A	Inspected
Instance on Room 235	Inspected
Instance on Room 415A	Inspected
Instance on Room 511A	Inspected
<b>Pendant Mounted</b>	
Instance on Room 128A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 235	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 415A	Does not exist

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X400**

Question	Response
<b>SCIENCE PREP ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Instance on Room 511A	Does not exist
<b>Surface Mounted</b>	
Instance on Room 128A	Does not exist
Instance on Room 235	Does not exist
Instance on Room 415A	Does not exist
Instance on Room 511A	Does not exist
<b>Recessed Mounted</b>	
Instance on Room 128A	Does not exist
Instance on Room 235	Does not exist
Instance on Room 415A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 511A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
Instance on Room 128A	Does not exist
Instance on Room 235	Does not exist
Instance on Room 415A	Does not exist
Instance on Room 511A	Does not exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 128A	Does not exist
Instance on Room 235	Does not exist
Instance on Room 415A	Does not exist
Instance on Room 511A	Does not exist
<b>Lighting Fixture - LED</b>	
Instance on Room 128A	Does not exist
Instance on Room 235	Does not exist
Instance on Room 415A	Does not exist
Instance on Room 511A	Does not exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 128A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 235	Does not exist
Instance on Room 415A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 511A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room 128A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 235	Does not exist
Instance on Room 415A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X400**

Question	Response
<b>SCIENCE PREP ROOM</b>	
<b>Emergency Shut-Off Power</b>	
Instance on Room 511A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	
Instance on Room 128A	Does not exist
Instance on Room 235	Does not exist
Instance on Room 415A	Does not exist
Instance on Room 511A	Does not exist
<b>SWIMMING POOL</b>	
<b>TOILET ROOM - STAFF</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - HID</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Lighting Fixture - LED</b>	
<b>TOILET ROOM - STUDENT</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
<b>Recessed Mounted</b>	
<b>Lighting Fixture - HID</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Lighting Fixture - LED</b>	
<b>Pendant Mounted</b>	
Condition	1- Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
<b>Recessed Mounted</b>	
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	
<b>EMERGENCY GENERATOR SET</b>	
<b>Automatic Transfer Switch (ATS)</b>	
Instance	Electrical Room 014
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO

**NYC Department of Education**  
**Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X400**

Question	Response
<b>EMERGENCY GENERATOR SET</b>	
<b>Automatic Transfer Switch (ATS)</b>	
EquipmentId	Transfer Switch
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Inspector Estimate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Generator Room 012A
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Caterpillar
EquipmentId	Exit Lights
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Generator Room 012A
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Caterpillar
EquipmentId	Fire Alarm
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Generator Room 012A
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Caterpillar
EquipmentId	Purge Mode
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room Inside Mechanical Room 027
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	EATON
EquipmentId	Transfer Switch
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented



**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X400**

Question	Response
<b>EMERGENCY GENERATOR SET</b>	
<b>Automatic Transfer Switch (ATS)</b>	
Deficiency	No deficiencies recorded
Instance	Water Main Room 030
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Master Control Systems
EquipmentId	Automatic Transfer Switch
Capacity/Size Quantity	50
Capacity/Size UOM	HP
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Battery Charger</b>	Inspected
Instance	Generator Room 012A
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Charles Industries
EquipmentId	Battery Charger
Capacity/Size Quantity	6
Capacity/Size UOM	AmpsDC
Capacity/Size 2 Quantity	24
Capacity/Size 2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Emergency Distribution Board</b>	Inspected
Number of Spares	10
<b>Fused Disconnect Switch Type</b>	Does not exist
<b>Molded Case Circuit Breaker Type</b>	Inspected
Instance	Electrical Room 014
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	EMP
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Diesel</b>	Inspected
Instance	Generator Room 012A
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Caterpillar
EquipmentId	Emergency Generator
Capacity/Size Quantity	375

**NYC Department of Education**  
**Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X400**

<b>Question</b>	<b>Response</b>
<b>EMERGENCY GENERATOR SET</b>	
<b>Diesel</b>	
Capacity/Size UOM	kVA
Capacity/Size 2 Quantity	300
Capacity/Size 2 UOM	kW
Capacity/Size 3 Quantity	1,041
Capacity/Size 3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Natural Gas</b>	Does not exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	
<b>EMERGENCY LIGHTING</b>	
<b>Battery Pack</b>	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	
Condition	Inspected
Deficiency	3- Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Gymnasium 1st and 5th Floor
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Violations	35672135R
<b>EXIT LIGHT</b>	
<b>Battery Pack</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Nearby Exit 5
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Non Battery Pack</b>	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
<b>EXIT/EMERGENCY LIGHT</b>	
<b>FIRE ALARM SYSTEM</b>	
<b>Bell/Horn</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X400**

<b>Question</b>	<b>Response</b>
<b>FIRE ALARM SYSTEM</b>	
<b>Duct Smoke Detector</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Area Smoke Detector</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Heat Detector</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Magnetic Door Holder/Contactor</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fused Cutout Panel</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Does not exist
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
Model	EST 3
EquipmentId	Fire Command Center
Installation Year	2018
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not exist
<b>Sub-Panel</b>	Does not exist
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not exist
<b>Panel</b>	Inspected
Condition	3- Fair
Deficiency	PANEL NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office - Room 023
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>Printer</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X400**

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Remote Annunciator</b>	
<b>Punch Register</b>	Does not exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>INTERCOM SYSTEM</b>	Inspected
<b>Elevator</b>	Inspected
Condition	1- Good
Deficiency	NOT CONNECTED TO REMOTE MONITORING STATION
Deficiency Location/Instance	Elevator ID: 2P88, 2P89
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
<b>Holding Area</b>	Does not exist
<b>LAN</b>	Inspected
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>MOTOR CONTROLLER</b>	Inspected
<b>MOTOR CONTROL CENTER</b>	Does not exist
<b>MOTOR STARTER/CONTACTOR</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Variable Frequency Drive</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Does not exist
<b>Fused Knife Switch Type</b>	Does not exist
<b>Fused Toggle Switch Type</b>	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room 014
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X400**

<b>Question</b>	<b>Response</b>
<b>PANEL BOARD</b>	
<b>Fused Toggle Switch Type</b>	
Violations	No violations recorded
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	3- Fair
Deficiency	NO SPARE
Deficiency Location/Instance	Nearby Room 315A, 219
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Instance	Room 119
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	QSC Model ISA 500Ti
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>SECURITY</b>	Inspected
<b>IPDVS/CCTV System</b>	Inspected
Condition	2- Between Good and Fair
Installation Year	2019
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Intrusion Alarm System</b>	Inspected
<b>Central Control Panel</b>	Inspected
Instance	Custodian's Office - Room 023
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2003
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	Inspected
Condition	3- Fair
Deficiency	SENSOR NOT OPERATIONAL
Deficiency Location/Instance	Exit 11, Clinic Room 015
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
<b>Panic Switch</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X400**

Question	Response
<b>SECURITY</b>	
<b>Intrusion Alarm System</b>	
<b>Siren/Strobe</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>Lighting - Security</b>	
Condition	3- Fair
Deficiency	No deficiencies recorded
<b>SERVICE SWITCH</b>	
	Inspected
Instance	Electrical Meter Room 032
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	EM DISTR. PANEL
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Meter Room 032
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	Fire Pump
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Meter Room 032
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	Main Switch
Capacity/Size Quantity	3000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>SWITCHBOARD</b>	
	Inspected
Number of Spares	0
<b>Fused Disconnect Switch Type</b>	
	Inspected
Instance	Electrical Room 014
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	N/A
Capacity/Size Quantity	3000

**NYC Department of Education**  
**Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X400**

Question	Response
<b>SWITCHBOARD</b>	
<b>Fused Disconnect Switch Type</b>	
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	4
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not exist
<b>Molded Case Circuit Breaker Type</b>	Does not exist
<b>TELEPHONE SYSTEM</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	Does not exist