

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Mechanical Inspection**

**X426**

Asset: **CHILDS HS AF - BRONX, 774 EAST GUN HILL ROAD, BRONX, NY, 10467**

Inspection Id	Inspection Type	Time In	Last Edited
2026	MECHANICAL	2023-12-27 07:57AM	2024-02-01 01:33PM

**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	No System Upgraded
Are there fuel tanks?	No
Total # of water main service entries to the asset	0
MERs/Fan Rooms Locations	None
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Painted/Obstructed Sprinkler Heads?	No
Are there any Emergency Stop Switches with Missing Hammers?	No components

**Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No condition recorded							

**Inspection**

Question	Response
<b>Mechanical</b>	
<b>AIR CONDITIONING</b>	Under construction
<b>CENTRAL ACID WASTE NEUTRALIZING TANK</b>	Does not exist
<b>CLIMATE CONTROL SYSTEM</b>	Under construction
<b>COMPACTOR</b>	Does not exist
<b>CONVEYING</b>	Under construction
<b>DOMESTIC WATER SYSTEM</b>	Under construction
<b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>	Under construction
<b>DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)</b>	Does not exist
<b>FIXTURES</b>	Under construction
<b>GAS FIRED FURNACE</b>	Under construction
<b>GAS SERVICE</b>	Under construction
<b>HEATING</b>	Under construction
<b>HEATING PLANT</b>	Inspected
Instance on 1st Floor	Under construction
<b>Enclosed IDF Room</b>	Does not exist
<b>KITCHEN</b>	Does not exist
<b>MDF Room</b>	Does not exist
<b>SCIENCE DEMO ROOM</b>	Does not exist
<b>SCIENCE LAB</b>	Does not exist
<b>SCIENCE PREP ROOM</b>	Does not exist
<b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>	Under construction
<b>SWIMMING POOL</b>	Does not exist
<b>VENTILATION</b>	Under construction