

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Electrical Inspection**

**X451**

**Asset:** STEVENSON HS AF - BRONX, 1980 LAFAYETTE AVENUE, BRONX, NY, 10473

Inspection Id	Inspection Type	Time In	Last Edited
5087	ELECTRICAL	2024-05-02 12:05PM	2024-05-02 07:47PM

**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	No System Upgraded
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	No
Water Penetration In Electrical Room?	No

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

**Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No condition recorded							

**Inspection**

Question	Response
<b>Electrical</b>	
<b>ATHLETIC FIELD</b>	Under construction
<b>AUDITORIUM</b>	Does not exist
<b>CAFETERIA</b>	Does not exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	Under construction
<b>COMPUTER LAB</b>	Does not exist
<b>GYMNASIUM</b>	Does not exist
<b>KITCHEN</b>	Does not exist
<b>LIBRARY</b>	Does not exist
<b>LOCKER ROOM</b>	Does not exist
<b>MULTIPURPOSE ROOM</b>	Does not exist
<b>SCIENCE DEMO ROOM</b>	Does not exist
<b>SCIENCE LAB</b>	Does not exist
<b>SCIENCE PREP ROOM</b>	Does not exist
<b>SWIMMING POOL</b>	Does not exist
<b>TOILET ROOM - STAFF</b>	Under construction
<b>TOILET ROOM - STUDENT</b>	Under construction
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Does not exist
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not exist
<b>EMERGENCY GENERATOR SET</b>	Does not exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Does not exist
<b>EMERGENCY LIGHTING</b>	Does not exist
<b>EXIT LIGHT</b>	Does not exist
<b>EXIT/EMERGENCY LIGHT</b>	Does not exist
<b>FIRE ALARM SYSTEM</b>	Does not exist
<b>GROUNDING SYSTEM</b>	Under construction
<b>INTERCOM SYSTEM</b>	Does not exist
<b>LAN</b>	Does not exist
<b>LIGHTNING PROTECTION</b>	Does not exist
<b>MOTOR CONTROLLER</b>	Inspected
<b>MOTOR CONTROL CENTER</b>	Does not exist
<b>MOTOR STARTER/CONTACTOR</b>	Under construction

**NYC Department of Education**  
**Building Condition Assessment Survey 2023-2024**

***Electrical Inspection***

**X451**

<b>Question</b>	<b>Response</b>
<b>MOTOR CONTROLLER</b>	
<b>Variable Frequency Drive</b>	Does not exist
<b>PANEL BOARD</b>	Under construction
<b>PUBLIC ADDRESS SYSTEM</b>	Does not exist
<b>SECURITY</b>	Inspected
<b>IPDVS/CCTV System</b>	Does not exist
<b>Intrusion Alarm System</b>	Under construction
<b>Lighting - Security</b>	Does not exist
<b>SERVICE SWITCH</b>	Under construction
<b>SWITCHBOARD</b>	Does not exist
<b>TELEPHONE SYSTEM</b>	Does not exist
<b>TRANSFORMER</b>	Does not exist