## NYC Department of Education

## **Building Condition Assessment Survey 2023-2024**

Asset:	STEVENSO	N HS AF - BRONX, 1980 L	AFAYETTE AVEN	UE, BRONX, NY	7, 10473		
Inspection Id	d Inspection Ty	pe			Time	In	Last Edited
509	93 MECHANICA	AL .			2024-05-01 09:11AM		M 2024-06-21 01:08PM
sset Data							
Question				Answer			
Have any Systems/Major Building Components been upgraded?				Systems:	Student's Fixt	tures - Lavatory	r/Sink
				Years:	2018		
				Systems:	Fixtures - Toi	lets, Urinals	
				Years:	2015		
Are there fuel tanks?				No 1			
	Total # of water main service entries to the asset						
	MERs/Fan Rooms Locations						
		sing or Defective CO Detectors?		No No			
	Are there any Painted/Obstructed Sprinkler Heads?  Are there any Emergency Stop Switches with Missing Hammers?				nents		
Priority Cond		2tenes with Missing Hamille		No compo	,1101110		
	riority	Condition	Component	Location	Person(s)	Person(s)	Photo
	Category	Description	Affected	Description	Notified	Title	Image
No condition							
	riccoraca						
Inspection				Response			
Question				Kesponse	;		
Mechanical				D	:-4		
AIR CONDITIONING				Does not o			
CENTRAL ACID WASTE NEUTRALIZING TANK				Does not			
CLIMATE CONTROL SYSTEM				Does not			
COMPACTOR				Does not			
CONVEY	ING			Does not	exist		
DOMEST	TIC WATER SYST	ГЕМ		Inaccessib	ole		
DRAIN/W	VASTE/VENT AN	D STORM SYSTEM		Inaccessib	ole		
DUAL TE	EMPERATURE SY	YSTEM (CHILLED AND HO	Γ WATER)	Does not	exist		
FIXTURE	ES			Inaccessib	ole		
GAS FIRI	ED FURNACE			Does not	exist		
GAS SER	GAS SERVICE			Does not	exist		
HEATING	G			Inaccessib	ole		
HEATING	G PLANT			Does not	exist		
Enclosed IDF Room			Does not	exist			
	KITCHEN			Does not	exist		
MDF Roo				Does not	exist		
	E DEMO ROOM			Does not	exist		
SCIENCE				Does not			
	E PREP ROOM			Does not			
		F FIDE SYSTEM		Does not			
-		E, FIRE SYSTEM		Does not			
	NG POOL						
VENTILA	ATION			Inaccessib	oie		