NYC Department of Education

Building Condition Assessment Survey 2023-2024

Mechanical Inspection	X456

1echanical In	spection								X45		
Asset:	TRUMAN HS	S AF - BRONX, 750 BAYCHI	ESTER AVENUE,	BRONX, NY, 1	10475						
Inspection Id Inspection Type					Time	Time In			Last Edited		
1556	MECHANICAI	L			2023-	-12-08 07:23Al	M 2024	1-05-07	12:34PM		
sset Data											
Question				Answer							
Have any Systems/Major Building Components been upgraded?				No Syster	m Upgraded						
Are there fuel tanks?				No							
Total # of water main service entries to the asset				0							
MERs/Fan Ro				None							
		ng or Defective CO Detectors?		No							
		d Sprinkler Heads?		No							
		Switches with Missing Hammers?		No compo	onents						
<i>riority Condi</i> Exist Pri	ority	Condition	Component	Location	Person(s)	Person(s)	Photo				
	tegory	Description	Affected	Description	Notified	Title	Image				
No condition r	· ·	•		•							
Inspection											
Ouestion				Response	<u> </u>						
Mechanical				Tiesponse.							
AIR COND	ITIONING			Does not	exist						
CENTRAL ACID WASTE NEUTRALIZING TANK				Does not exist							
CLIMATE CONTROL SYSTEM				Does not exist							
COMPACTOR				Does not exist							
CONVEYIN	NG			Does not	exist						
DOMESTIC	C WATER SYSTI	EM		Does not	exist						
DRAIN/WASTE/VENT AND STORM SYSTEM				Does not exist							
DUAL TEM	IPERATURE SY	STEM (CHILLED AND HOT W	VATER)	Does not	exist						
FIXTURES				Does not exist							
GAS FIRED FURNACE				Does not	exist						
GAS SERVICE				Does not	exist						
HEATING				Does not	exist						
HEATING 1	PLANT			Does not	exist						
Enclosed ID	F Room			Does not	exist						
KITCHEN				Does not	exist						
MDF Room				Does not	exist						
SCIENCE I	DEMO ROOM			Does not	exist						
SCIENCE I	LAB			Does not	exist						
SCIENCE I	PREP ROOM			Does not	exist						
SPRINKLE	RS, STANDPIPE	E, FIRE SYSTEM		Does not	exist						
				ъ .							
SWIMMIN	G POOL			Does not	exist						