Building Condition Assessment Survey 2023-2024

Electrical Inspection

Asset:	3K CENTER	@ 1450 PLIMPTON AVE	NUE - BRONX, 145	U PLIMPTON A	VENUE, BRO	NX, NY, 1045	52
Inspectio	on Id Inspection Typ	e			Time I	n	Last Edited
	4060 ELECTRICAL				2024-0	03-19 08:32AM	2024-04-04 01:47PM
Asset Data	l						
Questior	n			Answer			
Have any Systems/Major Building Components been upgraded?		,	Systems:	Service Switch	l		
				Years:	2023, 2016		
				Systems:	All Other Elec	trical Systems a	nd Components
				Years:	2023		
Type of S				Below Gro	ound		
	eractive Whiteboard (IV	· · · · · · · · · · · · · · · · · · ·		Yes			
	enetration In Electrical I		. ~	No			
		S IN FIRE RESCUE AREA	AS	n			
Question		sistance Areas, Fire Rescue Area	and/or Holding Poor		esponse es		
	uilding?	Sistance Areas, File Rescue Area	is, and/or moraling Roor		68		
		ailable in all of these spaces for	use during a fire?	Y	<i>'es</i>		
Are	e all dedicated intercom	s operational?		Y	es		
Priority Co	ondition						
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No condi	ition recorded						
Inspection	п						
Question				Response			
Electric				Kesponse			
				Deserveta			
	ETIC FIELD			Does not e			
	TORIUM			Does not e			
CAFE	TERIA			Does not e	xist		
CLAS	SROOM/CORRIDOR	ADMINISTRATIVE SPACE		Inspected			
Ligh	0			Inspected			
	es a Chandelier Exist?			No	•		
	ghting Fixture - Fluore	escent		Does not e			
	ghting Fixture - HID			Does not e			
	ghting Fixture - Incand	lescent		Does not e	xist		
	ghting Fixture - LED			Inspected	• .		
-	Pendant Mounted			Does not e	X1St		
S	Surface Mounted			Inspected 1- Good			
	Condition				· 11		
-	Deficiency				ncies recorded		
F	Recessed Mounted			Inspected 1- Good			
	Deficiency				ncies recorded		
	PUTER LAB			Does not e			
	NASIUM			Does not e	xıst		
KITC				Inspected			
	Instance on Cellar			Inspected			
Ligh	-			¥ . 4			
	Instance on Cellar			Inspected			
Lig	ghting Fixture - Fluore	escent			• .		
<u>.</u>	Instance on Cellar			Does not e	xıst		
Lig	ghting Fixture - HID			D	• ,		
<u> </u>	Instance on Cellar	• •		Does not e	xıst		
Lig	ghting Fixture - Incand	lescent		5	• ,		
	Instance on Cellar			Does not e	xıst		

Building Condition Assessment Survey 2023-2024

Electrical Inspection

rical Inspection		A400
Question	Response	
KITCHEN		
Lighting		
Lighting Fixture - LED		
Instance on Cellar	Inspected	
Pendant Mounted		
Instance on Cellar	Does not exist	
Surface Mounted		
Instance on Cellar	Does not exist	
Recessed Mounted		
Instance on Cellar	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
LIBRARY	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	-
Instance on 1st Floor	Inspected	
Lighting	1	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	-
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 1st Floor	Does not exist	
Projection System		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

Response	
A	
1- Good	
1- Good	
No deficiencies recorded	
-	
No deficiencies recorded	
Does not exist	
-	
No deficiencies recorded	
Does not exist	
Does not exist	
Inspected	
Inspected	
1- Good	
No deficiencies recorded	
Inspected	
No deficiencies recorded	
Inspected	
No deficiencies recorded	
Inspected	
No deficiencies recorded	
Inspected	
No deficiencies recorded	
Inspected	
1- Good	
	No deficiencies recordedInspected1- GoodNo deficiencies recordedDoes not existDoes not existInspectedInspected1- GoodNo deficiencies recordedDoes not existInspected1- GoodNo deficiencies recordedDoes not existInspected1- GoodNo deficiencies recordedDoes not existInspected1- GoodNo deficiencies recordedDoes not existDoes not existInspected1- GoodNo deficiencies recordedInspected1- GoodNo deficiencies recordedNo deficiencies recordedInspected1- GoodNo deficiencies recordedInspected1- GoodNo deficiencies recordedNo deficiencies recordedNo deficiencies recorded

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

icai Inspection	Δ48
uestion	Response
FIRE ALARM SYSTEM	
CO Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Does not exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Edwards System Technology
Model	EST3X
EquipmentId	Fire Alarm Control Panel
Installation Year	2023
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
	Inspected
Printer Condition	1- Good
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Holding Area	Does not exist
· · · · · · · · · · · · · · · · · · ·	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

	A400
Response	
Does not exist	
Inspected	
1- Good	
No deficiencies recorded	
Does not exist	
Inspected	
Does not exist	
Inspected	
1- Good	
No deficiencies recorded	
Inspected	
Does not exist	
Does not exist	
Does not exist	
Inspected	
1- Good	
No deficiencies recorded	
Inspected	
Telecom Room 104	
1- Good	
1	
EACH	
-	
Documented	
No deficiencies recorded	
Inspected	
2023	
Documented	
No deficiencies recorded	
Inspected	
Inspected	
Custodian's Office	
1- Good	
1	
EACH	
Vista - 128B	
2023	
Documented	
No deficiencies recorded	
Inspected	
1- Good	
No deficiencies recorded	
Inspected	
1- Good	
No deficiencies recorded	
_	
Inspected	
	Does not exist Inspected 1- Good No deficiencies recorded Does not exist Inspected Does not exist Inspected Ooes not exist Inspected Ooes not exist Inspected Does not exist Inspected Ispected Ispected Telecom Room 104 1- Good 1 EACH Bogen Multicom - 2000 2023 Documented No deficiencies recorded Inspected Inspected Inspected Inspected Inspected Inspected Inspected Inspected Inspected Inspected

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response	
SECURITY		
Intrusion Alarm System		
Siren/Strobe		
Condition	1- Good	
Deficiency	No deficiencies recorded	
Lighting - Security	Inspected 1- Good	
Condition		
Deficiency	No deficiencies recorded	
SERVICE SWITCH	Inspected	
Instance	Basement - Electrical Meter Room	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	All City Switchboard	
EquipmentId	CT Cabinet & Service Switch #5	
Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2023	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
· · · ·	Basement - Electrical Meter Room	
Instance Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Square D	
EquipmentId	Fire Pump	
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2016	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SWITCHBOARD	Inspected	
Number of Spares	5	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room C05	
Instance Condition	1- Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	All City Switchboard	
EquipmentId	MDB Sections #1, #2	
Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	2023	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	1- Good	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

1			
luestion	Response		
TELEPHONE SYSTEM			
PBX/Intercom			
Deficiency	No deficiencies recorded		
Standard	Inspected		
Condition	1- Good		
Deficiency	No deficiencies recorded		
TRANSFORMER	Does not exist		

SFO