

**NYC Department of Education  
Building Condition Assessment Survey 2023-2024**

**Mechanical Inspection**

**X601**

**Asset:** SMITH HS AF - BRONX, 333 EAST 151 STREET, BRONX, NY, 10451

| Inspection Id | Inspection Type | Time In            | Last Edited        |
|---------------|-----------------|--------------------|--------------------|
| 4744          | MECHANICAL      | 2024-04-15 07:07AM | 2024-05-21 12:50PM |

**Asset Data**

| Question   | Answer             |
|--|--------------------|
| Have any Systems/Major Building Components been upgraded?    | No System Upgraded |
| Are there fuel tanks?  | No                 |
| Total # of water main service entries to the asset           | 0                  |
| MERs/Fan Rooms Locations                                     | None               |
| Are there any spaces with Missing or Defective CO Detectors? | No                 |
| Are there any Painted/Obstructed Sprinkler Heads?            | No                 |
| Are there any Emergency Stop Switches with Missing Hammers?  | No components      |

**Priority Condition**

| Exist Last Year?      | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Photo Image |
|-----------------------|-------------------|-----------------------|--------------------|----------------------|--------------------|-----------------|-------------|
| No condition recorded |                   |                       |                    |                      |                    |                 |             |

**Inspection**

| Question   | Response       |
|--|----------------|
| <b>Mechanical</b>                                      |                |
| <b>AIR CONDITIONING</b>                                | Does not exist |
| <b>CENTRAL ACID WASTE NEUTRALIZING TANK</b>            | Does not exist |
| <b>CLIMATE CONTROL SYSTEM</b>                          | Does not exist |
| <b>COMPACTOR</b>                                       | Does not exist |
| <b>CONVEYING</b>                                       | Does not exist |
| <b>DOMESTIC WATER SYSTEM</b>                           | Does not exist |
| <b>DRAIN/WASTE/VENT AND STORM SYSTEM</b>               | Does not exist |
| <b>DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)</b> | Does not exist |
| <b>FIXTURES</b>  | Does not exist |
| <b>GAS FIRED FURNACE</b>                               | Does not exist |
| <b>GAS SERVICE</b>                                     | Does not exist |
| <b>HEATING</b>   | Does not exist |
| <b>HEATING PLANT</b>                                   | Does not exist |
| <b>Enclosed IDF Room</b>                               | Does not exist |
| <b>KITCHEN</b>   | Does not exist |
| <b>MDF Room</b>  | Does not exist |
| <b>SCIENCE DEMO ROOM</b>                               | Does not exist |
| <b>SCIENCE LAB</b>                                     | Does not exist |
| <b>SCIENCE PREP ROOM</b>                               | Does not exist |
| <b>SPRINKLERS, STANDPIPE, FIRE SYSTEM</b>              | Does not exist |
| <b>SWIMMING POOL</b>                                   | Does not exist |
| <b>VENTILATION</b>                                     | Does not exist |