Building Condition Assessment Survey 2023-2024

Asset:	P.S. 8 MINISCHOOL - BRONX, 3010 BRIC	GGS AVENUE, 1	BRONX, NY, 10	458	
Inspection Id				Time In	Last Edited
	64 MECHANICAL			2023-10-18 02:101	
sset Data					
Ouestion Out			Answer		
	stems/Major Building Components been upgraded?		Systems:	Fixtures - Toilets, Urinals	
Have any Sy	stems/Major Building Components been upgraded:		Years:	2022	
			Systems:	Gas Fired Furnace	
			Years:	2017	
Are there fue	el tanks?		No		
Total # of wa	ater main service entries to the asset		0		
	Rooms Locations		MER		
Are there an	y spaces with Missing or Defective CO Detectors?		No		
Are there an	y Painted/Obstructed Sprinkler Heads?		No		
Are there any	y Emergency Stop Switches with Missing Hammers?		No compo	onents	
Priority Cond	lition				
	Priority Condition	Component	Location	Person(s) Person(s)	Photo
Last Year?	Category Description	Affected	Description	Notified Title	Image
No condition	recorded				
Inspection					
Question			Response		
Mechanical			*		
	DITIONING		Inspected		
-	Water System		Does not o	exist	
-	water System ser Water Distribution: Piping, Pumps and Auxiliario	PS	Does not o		
	Coil in Ductwork		Does not o		
Cooling			Does not o	exist	
DX Split			Inspected		
Indoor	r Unit		Inspected		
Cond	lition		3- Fair		
	Deficiency		No deficie	encies recorded	
Outdo	or Unit		Inspected		
Cond	lition		3- Fair		
	Deficiency		No deficie	encies recorded	
Dry Coo	oler		Does not o	exist	
Package	d / Rooftop Unit		Does not o	exist	
Package	ed Terminal A/C		Does not o	exist	
	ant Leak Detection System		Does not o		
	ant Piping		Inspected		
Condit			3- Fair		
	Deficiency			encies recorded	
Return 1			Does not o		
	LACID WASTE NEUTRALIZING TANK		Does not o		
CLIMATI	E CONTROL SYSTEM		Does not o		
COMPAC	CTOR		Does not o	exist	
CONVEY	ING		Does not o	exist	
DOMEST	TIC WATER SYSTEM		Inspected		
Domesti	c Cold Water System		Does not o		
	c Hot Water System		Inspected		
	stic Hot Water Remote Storage Tank		Does not o		
	stic Water Heat Exchanger		Does not o		
-	ic Domestic Water Heater		Does not o		
Gas Fi	red Domestic Water Heater		Inspected		
	Instance		MER		

Building Condition Assessment Survey 2023-2024

Mechanical Inspection	X808

Question	Response	
DOMESTIC WATER SYSTEM		
Domestic Hot Water System		
Gas Fired Domestic Water Heater		
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Rheem / Ruud	
EquipmentId	N/A	
Capacity/Size Quantity	50	
Capacity/Size UOM	MBH Input	
Capacity/Size 2 Quantity	60	
Capacity/Size 2 UOM	Gallons	
Source of Capacity/Size	Documented	
Installation Year	2010	
Source of Installation Year	Custodial Staff	
Deficiency	No deficiencies recorded	
Oil Fired Domestic Water Heater	Does not exist	
Heat Pump Domestic Water Heater	Does not exist	
Domestic Water Distribution Piping	Inspected	
Condition	3- Fair	
Deficiency	DAMAGED/MISSING INSULATION	
Deficiency Location/Instance	MER	
Deficiency Quantity	20	
Quantity Uom	L.F.	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	DEFECTIVE VALVE	
Deficiency Location/Instance Deficiency Quantity	MER	
	l EACH	
Quantity Uom Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Does not exist	
Sewage/Waste/Vent Piping Condition	Inspected 3- Fair	
	No deficiencies recorded	
Deficiency		
Sewage Ejector Pump	Does not exist	
Sump Pump	Does not exist	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Does not exist	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
Student	Inspected	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection	X808
-----------------------	------

Question	Response
FIXTURES	
Student	
Drinking Fountain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Locker Room Shower	Does not exist
Sink And Fountain Combo Unit	Does not exist
Toilet	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not exist
Gas Meter Room Vent	Does not exist
Gas Pressure Booster	Does not exist
CO/Gas Leak Detection	Does not exist
HEATING	Inspected
Heating Coil In Ductwork	Does not exist
Hydronic Heating	Does not exist Does not exist
Radiator/Convector/Fin Tube	Does not exist Does not exist
Steam Heating Steam supplied by External Sources	Does not exist Does not exist
Unit Heater/Cabinet Heater	Inspected
Condition	5- Poor
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	MER
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
HEATING PLANT	Does not exist
Enclosed IDF Room	Does not exist
KITCHEN	Does not exist
MDF Room	Does not exist
	Does not exist
SCIENCE DEMO ROOM	
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected

Building Condition Assessment Survey 2023-2024

Mechanical Inspection X808

	1.	-000	
uestion	Response		
VENTILATION			
Is the building Mechanically ventilated?	Yes		
Exhaust Fan	Inspected		
Condition	3- Fair		
Approximate Total # of Fans	1-25		
Deficiency	No deficiencies recorded		
Heating And Ventilating Unit	Does not exist		
Metal Ductwork	Inspected		
Condition	3- Fair		
Are there any uninsulated ductwork by design in Mechanical rooms?	No		
Are there chain operated dampers?	No		
Deficiency	DAMAGED/MISSING INSULATION		
Deficiency Location/Instance	MER		
Deficiency Quantity	10		
Quantity Uom	L.F.		
Potential Action	MAINTENANCE		
Urgency of Action	PRIORITY 3		
Purpose of Action	LEVEL 2		
Violations	No violations recorded		
Supply Fan	Does not exist		
Unit Ventilator	Does not exist		