## **Building Condition Assessment Survey 2023-2024**

Mechanical	Inspection	X822
Asset:	P.S. 310 MINISCHOOL - BRONX, 260 WEST KINGSBRIDGE ROAD, BRONX, NY, 10463	

Inspection Id	Inspection Type				Time	In	Last Edited
1787					2023	-12-19 07:29A	M 2024-01-17 03:07PM
sset Data			-				
Question				Answer			
Have any Syste	ems/Major Building C	Components been upgraded	 d?	Systems:	Kitchen - Gre	ease Traps	
, ,	, c	1 10		Years:	2021		
				Systems:	Gas Fired Do	mestic Water H	eater
				Years:	2018		
				Systems:	Fixtures - To	ilets	
				Years:	2015		
Are there fuel t	tanks?			No			
Total # of wate	er main service entries	s to the asset		1			
MERs/Fan Roo	oms Locations			MER			
Are there any s	spaces with Missing o	or Defective CO Detectors	?	Yes			
Location(s)				MER			
	Painted/Obstructed Sp			No			
·		ches with Missing Hamme	rs?	No compo	onents		
riority Condit	tion						
	ority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year? Cat	tegory	Description	Affected	Description	Notified	Title	Image
No condition re	ecorded						
Inspection							
Question				Response	;		
Mechanical							
AIR CONDI	ITIONING			Inspected			
	ater System			Does not			
		: Piping, Pumps and Aux	iliaries	Does not	exist		
-	oil in Ductwork			Does not	exist		
Cooling To	ower			Does not	exist		
DX Split S	System			Inspected			
Indoor U	Jnit			Inspected			
Conditi	ion			3- Fair			
D	Deficiency			No defici	encies recorded	I	
Outdoor	Unit			Inspected	ļ.		
Conditi	ion			4- Betwee	en Fair and Poo	r	
D	<b>D</b> eficiency			UP TO 5	TONS:DEFEC	TIVE	
	Deficiency Location	/Instance		MER			
	Deficiency Quantity			2			
	Quantity Uom			EACH			
	Potential Action			REPAIR			
	Urgency of Action			PRIORIT			
	Purpose of Action			LEVEL 2			
	Violations				ions recorded		
Dry Cooler				Does not			
	/ Rooftop Unit			Does not			
	Terminal A/C			Does not			
	nt Leak Detection Sy	stem		Does not Inspected			
Refrigeran	nt l'iping			3- Fair			
Refrigeran Refrigeran				3- Faif	TD A MAGDIA	DIGLIL ATION	
Refrigeran Refrigeran Condition	n			DAMAG			
Refrigeran Refrigeran Condition D	n Deficiency	Instance			ED/MISSING I	INSULATION	
Refrigeran Refrigeran Condition D	n Deficiency Deficiency Location/			MER	ED/MISSING I	INSULATION	
Refrigeran Refrigeran Condition	n Deficiency				ED/MISSING I	INSULATION	

## **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection	X822
-----------------------	------

iunicui Inspection	Aue
Question	Response
AIR CONDITIONING	
Refrigerant Piping	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Does not exist
COMPACTOR	Does not exist
CONVEYING	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Inspected
Gravity System	Does not exist
Pressure Booster System	Does not exist
Water Service	Inspected
Instance	MER
Instance Condition	3- Fair
Instance Quantity	1 EACH
Instance Quantity Uom	
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION
	DEVICE
Deficiency Location/Instance	MER
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist  Does not exist
Domestic Water Heat Exchanger	
Electric Domestic Water Heater	Does not exist
Gas Fired Domestic Water Heater	Inspected
Instance	MER
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	A.O. Smith
EquipmentId	N/A
Capacity/Size Quantity	75
Capacity/Size UOM	MBH Input
Capacity/Size 2 Quantity	74
Capacity/Size 2 UOM Source of Capacity/Size	Gallons Documented
Installation Year	2018
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3- Fair

## **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection X822

nunicui Inspection		1022
Question	Response	
DRAIN/WASTE/VENT AND STORM SYSTEM		
Interior Storm Piping		
Deficiency	No deficiencies recorded	
Sewage/Waste/Vent Piping	Inspected	
Condition	3- Fair	
Deficiency	SEWAGE/WASTE PIPING:DEFECTIVE/LEAKS	
Deficiency Location/Instance	Room MS5	
Deficiency Quantity	10	
Quantity Uom	L.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Sewage Ejector Pump	Does not exist	
Sump Pump	Does not exist	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected  Does not exist	
Janitor Sink		
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
Student	Inspected	
Drinking Fountain	Does not exist	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not exist	
	Inspected	
Sink And Fountain Combo Unit		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
GAS FIRED FURNACE	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GAS SERVICE	Inspected	
	Inspected	
Gas Distribution Piping Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Does not exist	
Gas Meter Room Vent	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Pressure Booster	Does not exist	
CO/Gas Leak Detection	Does not exist	
HEATING	Inspected	
Heating Coil In Ductwork	Does not exist	

## **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection X822

inicui inspection		Λ04
nestion	Response	
HEATING		
Hydronic Heating	Does not exist	
Radiator/Convector/Fin Tube	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Heating	Does not exist	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Does not exist	
IEATING PLANT	Does not exist	
Enclosed IDF Room	Inspected	
Instance on Room across Room MS3	Inspected	
Dedicated A/C Equipment	<del>-</del>	
Instance on Room across Room MS3	Inspected	
Instance Condition	4- Between Fair and Poor	
Deficiency	DOES NOT EXIST	
Deficiency Location/Instance	Room across Room MS3	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	INSTALL	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
CO Detector		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Gas System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Grease Trap		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Hood		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Hood Fire Suppression System		
Instance on 1st Floor	Does not exist	
Hot Water Temperature Booster		
Instance on 1st Floor	Does not exist	
Kitchen Sink		
Instance on 1st Floor	Inspected	

## **Building Condition Assessment Survey 2023-2024**

Mechanical Inspection X822

uestion	Response	
KITCHEN		
Kitchen Sink		
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
MDF Room	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not exist	
Wet Sprinkler Alarm Valve Assembly	Does not exist	
Fire Booster Pump Assembly	Does not exist	
Roof Tank	Does not exist	
Siamese Connection	Does not exist	
Sprinkler Head	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Sprinkler Piping	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standpipe System	Does not exist	
Water Gong	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Yes	
Exhaust Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-25	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Does not exist	
Metal Ductwork	Inspected	
Condition	3- Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	Yes	
Are there chain operated dampers?	No	
Deficiency	DEFECTIVE REGISTER/DIFFUSER	
Deficiency Location/Instance	Room MS8	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Supply Fan	Does not exist	
Unit Ventilator	Does not exist	