

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X870

Asset: **P.S. 70 MINISCHOOL - BRONX, 1691 WEEKS AVENUE, BRONX, NY, 10457**

Inspection Id	Inspection Type	Time In	Last Edited
3269	MECHANICAL	2024-02-15 07:23AM	2024-03-25 09:40PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Fixtures - Drinking Fountains Years: 2020 Systems: Fixtures - Toilets, Urinals; Electric Domestic Water Heater Years: 2016
Are there fuel tanks?	No
Total # of water main service entries to the asset	0
MERs/Fan Rooms Locations	MER 9
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Painted/Obstructed Sprinkler Heads?	No
Are there any Emergency Stop Switches with Missing Hammers?	No components

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No condition recorded							

Inspection

Question	Response
Mechanical	
AIR CONDITIONING	Inspected
Chilled Water System	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork	Does not exist
Cooling Tower	Does not exist
DX Split System	Inspected
Indoor Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Outdoor Unit	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Does not exist
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Does not exist
COMPACTOR	Does not exist
CONVEYING	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Does not exist
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Inspected
Condition	2- Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X870

Question	Response
DOMESTIC WATER SYSTEM	
Domestic Hot Water System	
Electric Domestic Water Heater	
Deficiency	No deficiencies recorded
Gas Fired Domestic Water Heater	
	Does not exist
Oil Fired Domestic Water Heater	
	Does not exist
Heat Pump Domestic Water Heater	
	Does not exist
Domestic Water Distribution Piping	
Condition	Inspected
	3- Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	
	Inspected
Interior Storm Piping	
Condition	Inspected
	3- Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	
Condition	Inspected
	3- Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	
	Does not exist
Sump Pump	
Condition	Inspected
	3- Fair
Deficiency	No deficiencies recorded
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	
	Does not exist
FIXTURES	
	Inspected
Staff And Other	
	Inspected
Janitor Sink	
Condition	Inspected
	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	
Condition	Inspected
	3- Fair
Deficiency	No deficiencies recorded
Toilet	
Condition	Inspected
	2- Between Good and Fair
Deficiency	No deficiencies recorded
Urinal	
	Does not exist
Student	
	Inspected
Drinking Fountain	
Condition	Inspected
	1- Good
Deficiency	No deficiencies recorded
Lavatory/Sink	
Condition	Inspected
	3- Fair
Deficiency	No deficiencies recorded
Locker Room Shower	
	Does not exist
Sink And Fountain Combo Unit	
	Does not exist
Toilet	
Condition	Inspected
	2- Between Good and Fair
Deficiency	No deficiencies recorded
Urinal	
Condition	Inspected
	2- Between Good and Fair
Deficiency	No deficiencies recorded
GAS FIRED FURNACE	
Condition	Inspected
	3- Fair
Deficiency	No deficiencies recorded
GAS SERVICE	
	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Mechanical Inspection

X870

Question	Response
GAS SERVICE	
Gas Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not exist
Gas Meter Room Vent	Does not exist
Gas Pressure Booster	Does not exist
CO/Gas Leak Detection	Does not exist
HEATING	
	Inspected
Heating Coil In Ductwork	Does not exist
Hydronic Heating	Does not exist
Radiator/Convactor/Fin Tube	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Steam Heating	Does not exist
Steam supplied by External Sources	Does not exist
Unit Heater/Cabinet Heater	Does not exist
HEATING PLANT	
	Does not exist
Enclosed IDF Room	Does not exist
KITCHEN	
	Does not exist
MDF Room	Does not exist
SCIENCE DEMO ROOM	
	Does not exist
SCIENCE LAB	
	Does not exist
SCIENCE PREP ROOM	
	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	
	Does not exist
SWIMMING POOL	
	Does not exist
VENTILATION	
Is the building Mechanically ventilated?	Yes
Exhaust Fan	Inspected
Condition	3- Fair
Approximate Total # of Fans	1-25
Deficiency	No deficiencies recorded
Heating And Ventilating Unit	Does not exist
Metal Ductwork	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	No
Are there chain operated dampers?	No
Deficiency	No deficiencies recorded
Supply Fan	Does not exist
Unit Ventilator	Does not exist