Building Condition Assessment Survey 2023-2024

Asset:	P.S. 93 MINISO	CHOOL - BRONX, 1535 STO	DRY AVENUE, I	BRONX, NY, 104	473		
Inspection Id	Inspection Type				Time	In	Last Edited
3190	MECHANICAL				2024	-02-13 09:45AM	1 2024-03-30 02:21PM
set Data							
Question				Answer			
Have any Syste	ems/Major Building	Components been upgraded?		Systems:	Exhaust Fan;	Electric Domest	ic Water Heater
				Years:	2018		
Are there fuel	tanks?			No			
Total # of wate	er main service entri	es to the asset		1			
MERs/Fan Ro				MER			
		or Defective CO Detectors?		No			
	Painted/Obstructed S	sprinkler Heads? itches with Missing Hammers?		No No compo	manta		
		itches with Missing Hammers?		No compo	ments		
ority Condit							
	ority	Condition	Component	Location	Person(s)	Person(s)	Photo
	tegory	Description	Affected	Description	Notified	Title	Image
No condition re	ecorded						
spection							
Question				Response			
Mechanical							
AIR COND	ITIONING			Inspected			
Chilled Wa	ater System			Does not o	exist		
	v	n: Piping, Pumps and Auxiliarie	es	Does not o	exist		
Cooling Co	oil in Ductwork			Does not o	exist		
Cooling To	ower			Does not o	exist		
DX Split S	System			Does not o			
Dry Coole				Does not o			
Packaged / Rooftop Unit				Inspected			
-	nstance			MER			
_	nstance Condition			3- Fair			
_	nstance Quantity			2			
_	nstance Quantity Uo	m		EACH			
M	1anufacturer			York			
	equipmentId			N/A			
	Capacity/Size Quanti Capacity/Size UOM	ty		24 Tons			
	ource of Capacity/S	17e		Inspector	Estimate		
_	nstallation Year			2006	Littinate		
	ource of Installation	Year		Inspector	Estimate		
S	ource of Heating			N/A			
R	defrigerant Type			R-22			
D	Deficiency			No deficie	encies recorded		
Packaged	Terminal A/C			Does not o	exist		
Refrigerar	nt Leak Detection S	System		Does not o			
Refrigerar				Does not o			
Return Fa				Does not o			
		UTRALIZING TANK		Does not o			
CLIMATE (CONTROL SYSTE	EM		Does not o	exist		
COMPACT	OR			Does not o	exist		
CONVEYIN	NG			Does not o	exist		
	CAMATED CACTER	Λ.		Inspected			
DOMESTIC	. WAIEK SYSIEN	/I		mspeered			
	Cold Water System			Inspected			

Building Condition Assessment Survey 2023-2024

Mechanical Inspection X893

anicai Inspection	X8
estion	Response
DOMESTIC WATER SYSTEM	
Domestic Cold Water System	Y 1
Water Service	Inspected
Instance	MER
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Deficiency	WATER MAIN:MISSING BACKFLOW PREVENTION DEVICE
Deficiency Location/Instance	MER
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Gas Fired Domestic Water Heater	Does not exist
Oil Fired Domestic Water Heater	Does not exist
Heat Pump Domestic Water Heater	Does not exist
Domestic Water Distribution Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
PRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
	Does not exist
Interior Storm Piping Sewage/Waste/Vent Piping	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Does not exist
Sump Pump	Does not exist
UAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist
IXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Does not exist
Urinal	
Student Deiglière Ferreteir	Inspected
Drinking Fountain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	3- Fair

Building Condition Assessment Survey 2023-2024

Mechanical Inspection X893

Question	Response	
FIXTURES		
Student		
Lavatory/Sink		
Deficiency	CRACKED/PHYSICAL DAMAGE	
Deficiency Location/Instance	Girl's Toilet Room (2 of 5)	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Does not exist	
Toilet	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GAS FIRED FURNACE	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GAS SERVICE	Inspected	
	Inspected	
Gas Distribution Piping Condition	3- Fair	
Deficiency	No deficiencies recorded	
Gas Meter Room Exhaust Fan	Does not exist	
Gas Meter Room Exnaust Fan Gas Meter Room Vent	Does not exist	
Gas Pressure Booster	Does not exist	
CO/Gas Leak Detection	Does not exist	
HEATING	Inspected	
Heating Coil In Ductwork	Does not exist	
Hydronic Heating	Does not exist	
Radiator/Convector/Fin Tube	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Steam Heating	Does not exist	
Steam supplied by External Sources	Does not exist	
Unit Heater/Cabinet Heater	Does not exist	
HEATING PLANT	Does not exist	
Enclosed IDF Room	Does not exist	
KITCHEN	Does not exist	
MDF Room	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Does not exist	
SWIMMING POOL	Does not exist	
	Inspected	
VENTILATION Is the building Mechanically ventilated?	Yes	
Is the building Mechanically ventilated? Exhaust Fan	Inspected	
Exnaust Fan Condition	1- Good	
Approximate Total # of Fans	1-25	

Building Condition Assessment Survey 2023-2024

Mechanical Inspection X893

_				
nestion	Response			
VENTILATION				
Exhaust Fan				
Deficiency	No deficiencies recorded			
Heating And Ventilating Unit	Does not exist			
Metal Ductwork	Inspected			
Condition	3- Fair			
Are there any uninsulated ductwork by design in Mechanical rooms?	No			
Are there chain operated dampers?	No			
Deficiency	No deficiencies recorded			
Supply Fan	Does not exist			
Unit Ventilator	Does not exist			