

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X930

Asset: **P.S. 9 TEMP. C.R. BLDG. - BRONX, 230 EAST 183 STREET, BRONX, NY, 10458**

Inspection Id	Inspection Type	Time In	Last Edited
2615	MECHANICAL	2024-01-23 07:38AM	2024-02-28 08:51PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: Drinking Fountains Years: 2022 Systems: Exhaust Fans Years: 2021
Are there fuel tanks?	No
Total # of water main service entries to the asset	0
MERs/Fan Rooms Locations	None
Are there any spaces with Missing or Defective CO Detectors?	No
Are there any Painted/Obstructed Sprinkler Heads?	No
Are there any Emergency Stop Switches with Missing Hammers?	No components

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
		No condition recorded					

Inspection

Question	Response
Mechanical	
AIR CONDITIONING	Inspected
Chilled Water System	Does not exist
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not exist
Cooling Coil in Ductwork	Does not exist
Cooling Tower	Does not exist
DX Split System	Does not exist
Dry Cooler	Does not exist
Packaged / Rooftop Unit	Does not exist
Packaged Terminal A/C	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Assistant Principal Office, Room 6
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Refrigerant Leak Detection System	Does not exist
Refrigerant Piping	Does not exist
Return Fan	Does not exist
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not exist
CLIMATE CONTROL SYSTEM	Does not exist
COMPACTOR	Does not exist
CONVEYING	Does not exist
DOMESTIC WATER SYSTEM	Inspected
Domestic Cold Water System	Does not exist
Domestic Hot Water System	Inspected
Domestic Hot Water Remote Storage Tank	Does not exist
Domestic Water Heat Exchanger	Does not exist
Electric Domestic Water Heater	Inspected
Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Mechanical Inspection

X930

Question	Response
DOMESTIC WATER SYSTEM	
Domestic Hot Water System	
Electric Domestic Water Heater	
Deficiency	No deficiencies recorded
Gas Fired Domestic Water Heater	
	Does not exist
Oil Fired Domestic Water Heater	
	Does not exist
Heat Pump Domestic Water Heater	
	Does not exist
Domestic Water Distribution Piping	
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	
	Inspected
Interior Storm Piping	
	Does not exist
Sewage/Waste/Vent Piping	
Condition	Inspected
Deficiency	2- Between Good and Fair
	No deficiencies recorded
Sewage Ejector Pump	
	Does not exist
Sump Pump	
	Does not exist
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	
	Does not exist
FIXTURES	
	Inspected
Staff And Other	
	Inspected
Janitor Sink	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
Lavatory/Sink	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
Toilet	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
Urinal	
	Does not exist
Student	
	Inspected
Drinking Fountain	
Condition	Inspected
Deficiency	1- Good
	No deficiencies recorded
Lavatory/Sink	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
Locker Room Shower	
	Does not exist
Sink And Fountain Combo Unit	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
Toilet	
Condition	Inspected
Deficiency	3- Fair
	No deficiencies recorded
Urinal	
	Does not exist
GAS FIRED FURNACE	
	Does not exist
GAS SERVICE	
	Does not exist
HEATING	
	Inspected
Heating Coil In Ductwork	
	Does not exist
Hydronic Heating	
	Does not exist
Radiator/Convactor/Fin Tube	
	Does not exist
Steam Heating	
	Does not exist
Steam supplied by External Sources	
	Does not exist

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Mechanical Inspection

X930

Question	Response
HEATING	
Unit Heater/Cabinet Heater	Inspected
Condition	3- Fair
Deficiency	DEFECTIVE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
HEATING PLANT	Does not exist
Enclosed IDF Room	Does not exist
KITCHEN	Does not exist
MDF Room	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Does not exist
SWIMMING POOL	Does not exist
VENTILATION	Inspected
Is the building Mechanically ventilated?	Yes
Exhaust Fan	Inspected
Condition	1- Good
Approximate Total # of Fans	1-25
Deficiency	No deficiencies recorded
Heating And Ventilating Unit	Does not exist
Metal Ductwork	Inspected
Condition	3- Fair
Are there any uninsulated ductwork by design in Mechanical rooms?	No
Are there chain operated dampers?	No
Deficiency	No deficiencies recorded
Supply Fan	Does not exist
Unit Ventilator	Does not exist