NYC Department of Education

Building Condition Assessment Survey 2023-2024

Mechanical Inspection X941

Asset: P.S. 234 TRANSPORTABLE - I	NX, 2055 MAPES AVENUE, BRONX,	NY, 10460	
Inspection Id Inspection Type	, , , , , , , , , , , , , , , , , , , ,	Time In	Last Edited
3889 MECHANICAL		2024-03-12 09:39AM	2024-05-23 09:19PM
sset Data			
Question	Answer		
Have any Systems/Major Building Components been	aded? Systems	: Exhaust Fans (~75%)	
	Years:	2020	
	Systems	: Electric Domestic Water Heater	(1 of 2)
	Years:	2015	
Are there fuel tanks?	No		
Total # of water main service entries to the asset	0		
MERs/Fan Rooms Locations	0		
Are there any spaces with Missing or Defective CO D	ors? No		
Are there any Painted/Obstructed Sprinkler Heads?	No		
Are there any Emergency Stop Switches with Missing	nmers? No comp	onents	
riority Condition			
Exist Priority Condition	Component Location	Person(s) Person(s) I	Photo
Last Year? Category Description	Affected Description	Notified Title I	Image
No condition recorded			
Inspection			
	D		
Question	Respons	<u>e</u>	
Mechanical	.	1	
AIR CONDITIONING	Inspecte		
Chilled Water System	Does no		
Condenser Water Distribution: Piping, Pumps a	Auxiliaries Does no Does no		
Cooling Coil in Ductwork	Does no		
Cooling Tower DX Split System	Does no		
Dry Cooler	Does no		
Packaged / Rooftop Unit	Does no		
Packaged Terminal A/C	Inspecte	d	
Condition	3- Fair		
Deficiency	No defic	iencies recorded	
Refrigerant Leak Detection System	Does no	t exist	
Refrigerant Piping	Does no	t exist	
Return Fan	Does no	exist	
CENTRAL ACID WASTE NEUTRALIZING TA	Does no	t exist	
CLIMATE CONTROL SYSTEM	Does no	t exist	
COMPACTOR	Does no	t exist	
CONVEYING	Does no	t exist	
DOMESTIC WATER SYSTEM	Inspecte		
Domestic Cold Water System	Does no		
Domestic Hot Water System	Inspecte		
Domestic Hot Water System Domestic Hot Water Remote Storage Tank	Does no		
Domestic Water Heat Exchanger	Does no	t exist	
Electric Domestic Water Heater	Inspecte	d	
Condition	<u> </u>	een Good and Fair	
Deficiency		iencies recorded	
Gas Fired Domestic Water Heater	Does no		
Oil Fired Domestic Water Heater	Does no		
Heat Pump Domestic Water Heater	Does no		
Domestic Water Distribution Piping	Inspecte		
	Поресис		
Condition Condition	2- Betwe	een Good and Fair	

NYC Department of Education

Building Condition Assessment Survey 2023-2024

Mechanical Inspection	X941
-----------------------	------

uestion	Response	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Does not exist	
Sewage/Waste/Vent Piping	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not exist	
Sump Pump	Does not exist	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Does not exist	
Student	Inspected	
Drinking Fountain	Does not exist	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Does not exist	
Toilet	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
GAS FIRED FURNACE	Does not exist	
	Does not exist	
GAS SERVICE		
HEATING	Does not exist	
HEATING PLANT	Does not exist	
Enclosed IDF Room	Does not exist	
KITCHEN	Does not exist	
MDF Room	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Yes	
Exhaust Fan	Inspected 1- Good	
Condition Approximate Total # of Fans	1-25	
Deficiency	DEFECTIVE	
Deficiency Location/Instance	T-8 - Toilet Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Heating And Ventilating Unit	Does not exist	
Metal Ductwork	Inspected	
Condition	3- Fair	
Are there any uninsulated ductwork by design in Mechanical rooms?	No	
Are there chain operated dampers?	No	
Deficiency	No deficiencies recorded	
Supply Fan	Does not exist	

NYC Department of Education

Building Condition Assessment Survey 2023-2024

Mechanical Inspection		X941
Question	Response	
VENTILATION		

Does not exist

Unit Ventilator