Building Condition Assessment Survey 2023-2024

MORRIS HS TRANSPORTABLE - BRONX, 1110 BOSTON ROAD, BRONX, NY, 10456

Mechanical Inspection

Asset:

Asset.	monnis	IIS TRANSFORTABLE - DROMA	, 110 005101	, KOAD, DRON		,		
Inspectio	n Id Inspection 7	Гуре			Time	In	Last Edited	
	4665 MECHANIC	CAL			2024-	04-11 09:45AN	A 2024-04-12 02:16PM	
Asset Data								
Question	l			Answer				
Have any	Systems/Major Bui	Iding Components been upgraded?		Systems:	Electric Dom	estic Water Hea	ters (2 of 4)	
				Years:	2017			
Are there	Are there fuel tanks?			No				
Total # o	Total # of water main service entries to the asset			0				
	MERs/Fan Rooms Locations			None				
	Are there any spaces with Missing or Defective CO Detectors?			No				
		cted Sprinkler Heads? p Switches with Missing Hammers?		No No compo	manta			
		p Switches with Missing Hammers?		No compo	licitis			
Priority Co								
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo	
Last Year?	Category	Description	Affected	Description	Notified	Title	Image	
No condi	tion recorded							
Inspection	ı							
Question	1			Response				
Mechani	cal							
AIR C	ONDITIONING			Inspected				
Chilled Water System				Does not e	exist			
Condenser Water Distribution: Piping, Pumps and Auxiliaries			s	Does not e				
Cooling Coil in Ductwork				Does not e	exist			
Cooling Tower				Does not e	exist			
	plit System			Does not exist				
Dry Cooler				Does not e				
Packaged / Rooftop Unit				Does not e	exist			
Packaged Terminal A/C Condition			Inspected 3- Fair					
COL	Deficiency			No deficiencies recorded				
Rofri	Refrigerant Leak Detection System			Does not exist				
	Refrigerant Leak Detection System Refrigerant Piping			Does not exist				
Return Fan				Does not e	exist			
CENTRAL ACID WASTE NEUTRALIZING TANK				Does not exist				
CLIMATE CONTROL SYSTEM				Does not exist				
COMPACTOR				Does not e				
-	CONVEYING			Does not e				
DOMESTIC WATER SYSTEM				Inspected				
Domestic Cold Water System				Does not e	vist			
Domestic Cold water System Domestic Hot Water System				Inspected				
Domestic Hot Water System Domestic Hot Water Remote Storage Tank				Does not e	exist			
	Domestic Water Heat Exchanger			Does not e	exist			
Electric Domestic Water Heater				Inspected				
C	Condition			2- Betwee	n Good and Fai	r		
Deficiency				No deficie	encies recorded			
Gas Fired Domestic Water Heater				Does not e	exist			
Oil Fired Domestic Water Heater				Does not e	exist			
Heat Pump Domestic Water Heater				Does not e	exist			
Domestic Water Distribution Piping				Inspected				
	ndition			2- Betwee	n Good and Fai	r		
_	Deficiency			No deficie	encies recorded			
DRAI	N/WASTE/VENT A	ND STORM SYSTEM		Inspected				
	ior Storm Piping			Does not e				

X961

NYC Department of Education

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

unicui Inspection		
uestion	Response	
DRAIN/WASTE/VENT AND STORM SYSTEM		
Sewage/Waste/Vent Piping	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not exist	
Sump Pump	Does not exist	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Does not exist	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
Student	Inspected	
Drinking Fountain	Does not exist	
Lavatory/Sink	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not exist	
Sink And Fountain Combo Unit	Does not exist	
Toilet	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not exist	
GAS FIRED FURNACE	Does not exist	
GAS SERVICE	Does not exist	
HEATING	Does not exist	
HEATING PLANT	Does not exist	
Enclosed IDF Room	Does not exist	
KITCHEN	Does not exist	
	Does not exist	
MDF Room		
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Does not exist	
SWIMMING POOL	Does not exist	
VENTILATION	Inspected	
Is the building Mechanically ventilated?	Yes	
Exhaust Fan	Inspected	
Condition	3- Fair	
Approximate Total # of Fans	1-25	
Deficiency	No deficiencies recorded	
Heating And Ventilating Unit	Does not exist	
Metal Ductwork	Inspected 3- Fair	
Condition Are there any uninsulated ductwork by design in Mechanical rooms?	3- Fair No	
Are there chain operated dampers?	No	
Deficiency	No deficiencies recorded	
Supply Fan	Does not exist	

X961

NYC Department of Education

Building Condition Assessment Survey 2023-2024

Mechanical Inspection

X961 Question Response VENTILATION Unit Ventilator Does not exist