

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X973

Asset: M.S./H.S. 270 - BRONX, 1716 SOUTHERN BOULEVARD, BRONX, NY, 10460

Inspection Id	Inspection Type	Time In	Last Edited
2947	ELECTRICAL	2024-02-05 11:49AM	2024-03-05 03:05PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: LED Lighting (Multipurpose Room, Corridors), Exit/Emergency Light Years: 2022 Systems: IPDVS/CCTV System Years: 2020 Systems: Telephone System Years: 2016 Systems: LAN Years: 2008 Systems: All Other Electrical Systems and Components Years: 2005
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Emergency Generator Components - Not Operational	N/A	Emergency Generator - ATS	ATS Room B03	Montana Luciano	Cleaner	No Photo Taken

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Does not exist
CAFETERIA	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X973

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2005
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
COMPUTER LAB	Does not exist
GYMNASIUM	Does not exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X973

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LIBRARY	
Instance on Room 302	Inspected
Lighting	
Instance on Room 302	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 302	Inspected
Pendant Mounted	
Instance on Room 302	Does not exist
Surface Mounted	
Instance on Room 302	Does not exist
Recessed Mounted	
Instance on Room 302	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 302	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 302	Does not exist
Lighting Fixture - LED	
Instance on Room 302	Does not exist
Raceway With Receptacles	
Instance on Room 302	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 302	Does not exist
LOCKER ROOM	
Instance on Room 109	Inspected
Alternative Use	Yes
Instance on Room 105	Inaccessible
Lighting	
Instance on Room 109	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 109	Inspected
Pendant Mounted	
Instance on Room 109	Does not exist
Surface Mounted	
Instance on Room 109	Does not exist
Recessed Mounted	
Instance on Room 109	Inspected
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X973

Question	Response
LOCKER ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 109	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 109	Does not exist
Lighting Fixture - LED	
Instance on Room 109	Does not exist
MULTIPURPOSE ROOM	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	1- Good
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2005
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
SCIENCE DEMO ROOM	Inspected
Instance on Room 214	Inspected
Power Panel?	Yes
Alternative Use	Yes
Lighting	

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

X973

Question	Response
SCIENCE DEMO ROOM	
Lighting	
Instance on Room 214	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 214	Inspected
Pendant Mounted	
Instance on Room 214	Does not exist
Surface Mounted	
Instance on Room 214	Does not exist
Recessed Mounted	
Instance on Room 214	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 214	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 214	Does not exist
Lighting Fixture - LED	
Instance on Room 214	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 214	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 214	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 214	Inspected
Instructor Unit	
Instance on Room 214	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 214	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 214	Does not exist
SCIENCE LAB	
Instance on Rooms 314, 412	Inspected
Power Panel?	No
Alternative Use	No
Lighting	
Instance on Rooms 314, 412	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 314, 412	Inspected
Pendant Mounted	
Instance on Rooms 314, 412	Does not exist
Surface Mounted	
Instance on Rooms 314, 412	Does not exist
Recessed Mounted	
Instance on Rooms 314, 412	Inspected
Instance Condition	3- Fair

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X973

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Rooms 314, 412	Does not exist
Lighting Fixture - Incandescent	
Instance on Rooms 314, 412	Does not exist
Lighting Fixture - LED	
Instance on Rooms 314, 412	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Rooms 314, 412	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Rooms 314, 412	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Rooms 314, 412	Inspected
Instructor Unit	
Instance on Rooms 314, 412	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Rooms 314, 412	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Rooms 314, 412	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Rooms 314, 412	Does not exist
SCIENCE PREP ROOM	
Instance on Room 314A	Inspected
Power Panel?	No
Alternative Use	Yes
Instance on Room 412A	Inaccessible
Lighting	
Instance on Room 314A	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 314A	Inspected
Pendant Mounted	
Instance on Room 314A	Does not exist
Surface Mounted	
Instance on Room 314A	Does not exist
Recessed Mounted	
Instance on Room 314A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 314A	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X973

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - Incandescent	
Instance on Room 314A	Does not exist
Lighting Fixture - LED	
Instance on Room 314A	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 314A	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 314A	Does not exist
Power Supply	
Instance on Room 314A	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	ATS Room B03
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Detroit Diesel Spectrum
EquipmentId	Fire Alarm ATS
Capacity/Size Quantity	30
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X973

Question	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Installation Year	2005
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Water Service Room B02
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Metron Inc
EquipmentId	Fire Pump Automatic Transfer Switch
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2005
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	ATS Room B03
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Detroit Diesel Spectrum
EquipmentId	Generator ATS
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2005
Source of Installation Year	Documented
Deficiency	ATS NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Battery Charger	Inspected
Instance	Roof - Emergency Generator Enclosure
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Detroit Diesel Spectrum
EquipmentId	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size 2 Quantity	26
Capacity/Size 2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	2005
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Emergency Distribution Board	Inspected
Number of Spares	3
Fused Disconnect Switch Type	Inspected
Instance	ATS Room B03
Instance Condition	2- Between Good and Fair
Instance Quantity	1

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X973

Question	Response
EMERGENCY GENERATOR SET	
Emergency Distribution Board	
Fused Disconnect Switch Type	
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	EMDB
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Switchboard Mains Size
Installation Year	2005
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Molded Case Circuit Breaker Type	Does not exist
Diesel	Inspected
Instance	Roof - Emergency Generator Enclosure
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Detroit Diesel Spectrum
EquipmentId	Emergency Generator
Capacity/Size Quantity	281
Capacity/Size UOM	kVA
Capacity/Size 2 Quantity	225
Capacity/Size 2 UOM	kW
Capacity/Size 3 Quantity	781
Capacity/Size 3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2005
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Natural Gas	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Does not exist
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X973

Question	Response
FIRE ALARM SYSTEM	
Manual Pull Station	
Condition	3- Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Notifier
Model	AFP - 1010
EquipmentId	Interior Fire Alarm System
Installation Year	2005
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X973

Question	Response
FIRE ALARM SYSTEM	
Tamper Flow Switch/Chain	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	
	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	
	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	
	Does not exist
MOTOR CONTROLLER	
	Inspected
MOTOR CONTROL CENTER	
	Does not exist
MOTOR STARTER/CONTACTOR	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	
	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	
	Inspected
Instance	MDF Room 431
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Biamp MPA250
Installation Year	2005
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	
	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X973

Question	Response
SECURITY	
IPDVS/CCTV System	
Installation Year	2020
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	
	Inspected
Central Control Panel	
	Inspected
Instance	Custodian's Office - Room 117
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	2005
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	
	Inspected
Instance	Electrical Room B04
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	Service Switch #1
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2005
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B04
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	Service Switch #5 (Sprinkler Boost Pump)
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2005
Source of Installation Year	Documented

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X973

Question	Response
SERVICE SWITCH	
Deficiency	No deficiencies recorded
Instance	Electrical Room B04
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	Service Switch #4 (Feeds RDB)
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2005
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B04
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	Service Switch #3 (HDB)
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2005
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B04
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	Service Switch #2 (Feeds EMDB)
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2005
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	9
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room B04
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	HDB
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2005
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B04

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

X973

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	MDB Section #1, 2
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2005
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Roof - Room R01 - Electrical Room B
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	RDB
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2005
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist